1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

District IV

## State of New Mexico

Form C-144 June 1, 2004

**Energy Minerals and Natural Resources** 

Oil Conservation Division

Oil Conservation Division


1220 South St. Francis Dr. Nov 2004

For drilling and production facilities, submit to appropriate NMOCD District Office.

For downstream facilities, submit to Santa Fe office Santa Fe, NM 87505

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade ta Type of action: Registration of a pit	nk covered by a "general plan" Yes or below-grade tank Closure of a pit or	No Dejlow-grade tank X
Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP Telephone:	505-326-9700 English and tress a rice lank confirm	-inc.com
Address: 3401 E. 30TH STREET, FARMINGTON, NM 87402	- Colores	Formation: Basin Fruitland Coal
Facility or well name: Negro Canyon 100 API #:	30-045-32505 U/L or Otr/Otr M S	Sec 12 T 3IN R 8W
County: San Juan, NM Latitude 36.9078 Longitude		e Owner Federal X State Private Indian
Pit Type Drilling X Production Disposal  Workover Emergency Lined X Unlined Liner type: Synthetic X Thickness 12 mil Clay  Pit Volume bbl	Below-grade tank  Volume:bbl	
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) 20 points (10 points) ( 0 points)
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) ( 0 points) 0 points
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) ( 0 points) O points
	Ranking Score (Total Points)	20 points
If this is a pit closure: (1) attach a diagram of the facility showing the pit's relative your are burying in place) onsite	ity (3) Attach a g	general description of remedial action taken includingft. and attach sample results. (5)
· · · · · · · · · · · · · · · · · · ·	• • • • •	above-described pit or below-grade tank has ative OCD-approved plan
Date: 11/2/2004  Printed Name/Title Joni Clark, Sr. Regulatory Specialist  Your certification and NMOCD approval of this application/closure does not re otherwise endanger public health or the environment. Nor does it relieve the or regulations.		
Approval:    Carter of the Car	Signature Deury	Courf NOV - 8 2004



Blow pit overflow dike halfway between top and bottom and extend over plastic liner and into blow pit.

BURLINGTON RESOURCES OIL & GAS COMPANY LP

WORKOVER PIT DIAGRAM