Deviation Report

Name of Company	Address	
Burlington Resources Oil & Gas Company	P.O. Box 4289, Farmington, NM 87499	
Lease Name and Number (API Number)	Location	Sec. Twn. Rge.
SAN JUAN 27-5 UNIT #122P (30-039-27755)	1695 FNL -295 FWL	21-027N-005W
Pool and Formation	County	State
BASIN DAKOTA	RIO ARRIBA	NEW MEXICO

(OH)

Depth (ft)	Deviation (degrees)
60	0.75
120	1.00
565	0.50
1,065	0.75
1,565	2.25
1,779	1.00
2,246	1.00
2,738	1.50
3,237	1.00
- 3,532	1.25
7,752	0.50



Sean Conegar

Air Hammer Used? YES / NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 25th day of October, 2004.

Notary Public in and for San Juan County, New Mexico

My commission expires September 15, 2008.