

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

J. Thomas Development

3. Address and Telephone No.

c/o Jeff Davis P.O.Box 509 LaPlata N.M. 87418**(505) 327-9801**

4.

1180' FSL and 820' FWL, Sec. 33, T-31-N, R-14-W

5. Lease Designation and Serial No.

MOO-C-1420-4387

6. If Indian, Allottee or Tribe Name

If Unit or CA, Agreement Designation

8. Well Name and No.

Ute Mtn Ute 33-14

9. API Well No.

30 045 26835

10. Field and Pool, or Exploratory Area

Gallup

11. County or Parish, State

**San Juan County,
New Mexico**

12. CHECK APPROPRIATE BOX (s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment (Temporary)☐ Recompletion☐ Plugging Back☐ Casing Repair☐ Altering Casing☐ Other☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut-Off☐ Conversion to Injection☐ Dispose Water

(Note: Report results of multiple completion on Completion or Recompletion Report and Log form.)

13. Describe Proposed or completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

J. Thomas Development plugged and abandoned this well on Sept 23, 2004 as per the attached report.**SEE ATTACHED
CONDITIONS OF APPROVAL****RECEIVED****OCT 20 2004****Bureau of Land Management
Durango, Colorado**

14. I hereby certify that the foregoing is true and correct

Signed

Jeff DavisTitle **Agent**Date **10/21/04**

(This space for Federal or State office use)

Approved By

(s) Dan Robinson**ACTING**

Title

MINERALS STAFF CHIEF

Date

NOV 1 2004

Conditions of approval, if any:

RM000

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 * fax: 505-325-1211

J. Thomas Development
Ute Mountain Ute #33-14

September 24, 2004

Page 1 of 1

1180' FSL & 820' FWL, Section 33, T-31-N, R-14-W.
San Juan County, NM
Lease Number: MOO-C-1420-4387
API #30-045-26835

Plug & Abandonment Report

Summary:

Notified Colorado BLM on 9/21/04
Notified Ute Mountain Ute Tribe on 9/21/04

- 9/21/04 MOL and RU. Install pit liner and fence pit. Well pressures: 0# tubing, 80# casing. Lay relief line to pit. Blow down. Unseat pump and pull rods. LD 58 7/8" and 131 - 3/4" rods. ND wellhead. NU BOP, test. TOH with 150 joints 2-7/8" EUE tubing, 4850'. Round trip a 5-1/2" casing scraper to 4462'. Shut in well.
- 9/22/04 TIH and set 5-1/2" CR at 4429'. Pressure test the tubing to 1000#; held OK. Sting out of CR. Load and circulate well clean with 103 bbls of water. Pressure test casing to 1000#, held OK.
Plug #1 with CR at 4429', spot 16 sxs Type III cement (21 cf) inside the casing above the CR up to 4271' to isolate the Gallup perforations.
PUH to 2457. Connect pump line to the bradenhead and pressure test then BH annulus to 300#; held OK.
Plug #2 with 17 sxs Type III cement (22 cf) inside casing from 2457' to 2289' to cover the Mesaverde top.
PUH to 905'.
Plug #3 with 18 sxs Type III cement (24 cf) inside the casing from 905' to 727' to cover the Pictured Cliffs top.
PUH to 485'.
Plug #4 with 53 sxs Type III cement (70 cf) inside the casing from 485' to the surface to cover the Fruitand top and the surface casing shoe, circuyalte good cement out the casing valve. TOH and LD tubing.
- 9/23/04 RD rig. ND BOP. Cut off well head. Install P&A marker with 15 sxs cement. MOL. No Colorado BLM representative was on location.
H. Post with J. Thomas Development was on location.

J. Thomas Development
Tribal Lease: MOO-C-1420-4387
Well: Ute Mountain Ute #33-14
Location: 1180' FSL & 820' FWL
Sec. 33, T. 31 N., R. 14 W.
San Juan County, New Mexico

3160

Conditions of Approval - Subsequent Report of Abandonment

1. Approval of this Notice is for the completed down-hole plugging of the well. Surface reclamation must be completed as outlined in the Conditions of Approval attached to the approval for plugging and abandonment.
2. When the wellsite is ready for final surface inspection, please contact this office and the Ute Mountain Ute Energy Office in order that an onsite inspection can be made. Final Abandonment Notice (FAN) can be submitted via Sundry Notice at that time.
3. After the FAN is approved by this office, your liability associated with the subject well will terminate.