District 1 1625 N. French Dr., Hobbs, NM 88240 District II

1301 W. Grand Avenue, Artesia, NM 88210

District III 1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy Minerals and Natural

Oil Conservation Division

1220 South St. Francis Di Santa Fe, NM 87505


Form C-144 June 1, 2004

For drilling and production facilities, submit to appropriate NMOCD District Office.

For downstream facilities, submit to Santa Fe office

Pit or Below-Grade Tank Registration or Closure Is pit or below-grade tank covered by a general plan"? Yes X No

Type of action: Registration of a pit	or below-grade tank Colosure of a pit or	below-grade tank X
Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP Telephone	: 505-326-9700 e-mail address: jclark@br	-inc.com
Address: 3401 E. 30TH STREET, FARMINGTON, NM 87402		Formation: Basin Fruitland Coal
Facility or well name: Hale 350S API #:	30-045-31992 U/L or Qtr/Qtr E	Sec 27 T 31N R 8W
County: San Juan, NM Latitude 36.8712 Longitude	107.6674 NAD: 1927 X 1983 Surfac	e Owner Federal X State Private Indian
Pit Type: Drilling X Production Disposal Workover Emergency Lined X Unlined Liner type: Synthetic X Thickness 12 mil Clay Pit Volume bbl	Below-grade tank  Volume: bbl Type of fluid:  Construction material:  Double-walled, with leak detection? Yes If	If not, explain why not.
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) 20 points (10 points) ( 0 points)
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) ( 0 points) 0 points
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) ( 0 points) 0 points
	Ranking Score (Total Points)	20 points
If this is a pit closure: (1) attach a diagram of the facility showing the pit's re your are burying in place) onsite	ity (3) Attach a	general description of remedial action taken including
I hereby certify that the information above is true and complete to the best of a been/will be constructed or closed according to NMOCD guidelines	signature X, or an (attached) alternative Signature	of the pit or tank contaminate ground water or
Approval:  DEPUTY OIL & GAS INSPECTOR, DIST. AND Printed Name/Title	Signature Long	Dec 1 DEC - 2 2004



Blow pit overflow dike halfway between top and bottom and extend over plastic liner and into blow pit.

BURLINGTON RESOURCES OIL & GAS COMPANY LP
WORKOVER PIT DIAGRAM