

Deviation Report

Name of Company Burlington Resources Oil & Gas Company	Address P.O. Box 4289, Farmington, NM 87499	
Lease Name and Number (API Number) SEYMOUR #723S (30-045-32561)	Location -1665 FSL 1005 FEL	Sec. Twn. Rge. 25-031N-009W
Pool and Formation FRUITLAND COAL	County SAN JUAN	State NEW MEXICO

(OH)

<u>Depth (ft)</u>	<u>Deviation (degrees)</u>
312	0.25
812	1.00
1,302	3.00
1,404	2.00
1,466	2.00
1,714	2.25
1,959	1.75
2,428	2.00
2,842	2.75

Air Hammer Used? YES / NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Robert B. Tully

Subscribed and sworn to before me this 13th day of December, 2004.

Joan E. Clark

Notary Public in and for San Juan County, New Mexico

My commission expires March 31, 2006.

