

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test 128 7004 Operator SG INTERESTS I Ltd API #30-0 31-20892				
Property Name CORRALES		Location: Unit_0		
Well Status(Shut-In or Producing) Tubing Intermediate Casing Bradenhead				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	5 <sup>#</sup>	Steady Flow		
10 minutes	5	Surges		
15 minutes	5#	Down to Nothin	g	
20 minutes_		Nothing	NoFlow	)
25 minutes	5	Gas		
30 minutes		Gas & Water	7231172	
		Water	189011	
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK				
5 MINUTE SHUT-IN BRADENHEAD THE INTERMEDIATE				
REMARKS: Well is unepently on book team passint in test				
in new zone. Builed OB-head Walke is confirmed to be				
open.				
			· ·	
By Witness				
had Typouroe	·			