

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4-28-01 Operator Dugan Production Corp. API # 30-043-20406
Property Name DOME FED 29-22-6 Well No 2 Location: Unit K Section 29 Township 22N Range 06W
Well Status(Shut-In or Producing) Tubing 0 Intermediate _____ Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

| TIME | PRESSURES: | | | BRADENHEAD | INTERMEDIATE |
|------------|--------------|----------|-----------------|------------|--------------|
| | INTERMEDIATE | CASING | | FLOWED | FLOWED |
| 5 minutes | | <u>0</u> | Steady Flow | | |
| 10 minutes | | <u> </u> | Surges | | |
| 15 minutes | | <u> </u> | Down to Nothing | | |
| 20 minutes | | <u> </u> | Nothing | <u>X</u> | |
| 25 minutes | | <u>✓</u> | Gas | | |
| 30 minutes | | <u>0</u> | Gas & Water | | |
| | | | Water | | |

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:

By Danny Ray 32 Switcher (Position)
Witness _____

