NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT (Submit 2 copies to above address)

55.04 Operator Dugan Production Corp. API# Date of Test 30-043-20478 Property Name DOME NAV 34-22-6 Well No. 1 Location: Unit Section 34 Township 22N Range 06W Well Status(Shut-In or Producing) Tubing / Intermediate Casing Bradenhead OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH PRESSURES: **BRADENHEAD** INTERMEDIATE TIME **FLOWED** INTERMEDIATE CASING FLOWED 140 Steady Flow 5 mintues 10 minutes Surges 15 minutes Down to Nothing 20 minutes Nothing 140 25 minutes Gas 30 minutes Gas & Water Water If bradenhead flowed water, check all of the descriptions that apply below: SALTY **SULFUR 5 MINUTE SHUT-IN BRADENHEAD** INTERMEDIATE **REMARKS:** Ву Witness Switcher (Position)