

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 4-28-04 Operator Dugan Production Corp. API # 30-043-20483  
Property Name DOMED FED 29-22-6 Well No. 3 Location: Unit H Section 29 Township 22N Range 06W  
Well Status(Shut-In or Producing) Producing Tubing 0 Intermediate      Casing 100 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>110</u>	Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing	<u>X</u>	
25 minutes			Gas		
30 minutes		<u>100</u>	Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE     

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Danny Ray  
32 Switcher  
(Position)

Witness \_\_\_\_\_