

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5.19-04 Operator Dugan Production Corp. API # 30-043-20309
Property Name CHACRA Well No. 2 Location: Unit O Section 21 Township 22N Range 07W
Well Status(Shut-In or Producing) _____ Tubing 60 Intermediate _____ Casing 70 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>70</u>	Steady Flow		
10 minutes		<u>70</u>	Surges		
15 minutes		<u>70</u>	Down to Nothing		
20 minutes		<u>70</u>	Nothing	<u>X</u>	
25 minutes		<u>70</u>	Gas		
30 minutes		<u>70</u>	Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By  Witness _____
32 Switcher
(Position)