

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 5-19-04 Operator Dugan Production Corp. API # 30-043-20542  
Property Name DOMES TESORO 22 Well No. 4 Location: Unit C Section 22 Township 22N Range 07W  
Well Status(Shut-In or Producing) \_\_\_\_\_ Tubing 30 Intermediate \_\_\_\_\_ Casing 35 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>35</u>	Steady Flow		
10 minutes		<u>35</u>	Surges		
15 minutes		<u>35</u>	Down to Nothing		
20 minutes		<u>35</u>	Nothing	<u>X</u>	<u>X</u>
25 minutes		<u>35</u>	Gas		
30 minutes		<u>35</u>	Gas & Water		
			Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD 0

INTERMEDIATE \_\_\_\_\_

REMARKS:

By D. J. R. Witness \_\_\_\_\_

32

**Switcher**  
(Position)

