

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170


BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-26-01 Operator Dugan Production Corp. API # 30-043-20676
Property Name BALLYMALOE Well No 2 Location: Unit K Section 25 Township 23N Range 07W
Well Status(Shut-In or Producing) _____ Tubing 2 1/2 Intermediate _____ Casing 2 1/2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>260</u>	Steady Flow		
10 minutes		<u>260</u>	Surges		
15 minutes		<u>260</u>	Down to Nothing		
20 minutes		<u>260</u>	Nothing	X	
25 minutes		<u>260</u>	Gas		
30 minutes		<u>260</u>	Gas & Water		
			Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By [Signature] 32 Switcher
(Position) Witness _____