

CIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(606) 334-6176 FAX: (805) 334-6170
http://cmnrd.state.nm.us/ocd/District IM/2distric.htm

## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test	12-08-04	Operator_	ENERDYNE LLC	API #30-0	31-20433
Property Name_	CHACO WASI	Well No. 113	Location: Unit_P_	Section 21 Town	nship 20N Range_9W
Well Status(Shu	t-In or Producing	Tubing 5/8" In	ntermediate NA Cas	sing 5.5" Brande	enhead_NA
OPEN BRADE	ENHEAD AND IN	TERMEDIATE TO	ATMOSPHERE INDI	IVIDUALLY FOR	15 MINUTES EACH
PRESSURES:			BRADENHEAD		
INTERMEDIATE TIME <u>I</u>	NTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes			Steady Flow		
10 minutes		,	Surges		
15 minutes			Down to Nothi	ng	
20 minutes			Nothing		
25 minutes		**************************************	Gas		
30 minutes		<u> </u>	Gas & Water_		
			Water		91011/2/3
If bradenhead flow	ved water, check all	of the descriptions t	hat apply below:	ka Ka	0 Sc 200
CLEAR_	FRESH	_ SALTY	SULFUR BLA	ACK	
e minitude cultur	IN DDADENIE	AD	INTERMEDIATE		
	-IN BRADENHE	AD	INTERMEDIATE		
REMARKS: SH/	ALLOW MENEFEE	WELL THAT PRO	DUCES FRESH WATE	R WITH OIL- PROI	DUCTION CASING ONLY- NO
SUI	RFACE CASING O	R BRADENHEAD.			
***					The state of the s
	, , , , , , , , , , , , , , , , , , ,	**************************************			
By DON L. HANOSH		Witness			
MANAGING	MEMBER				
(Position)	<u> </u>				