

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12-20-04 Operator	ELM RIPSE REJAPI #30-0 43-20287
Property Name TRANSLA Well No. 6	ELM RIDGE RESAPI #30-0 43-20287 Location: Unit Section 29 Township 23/kange 4W
Well Status (Shut-In or Producing) Tubing	Intermediate Casing Bradenhead
OPEN BRADENHEAD AND INTERMEDIATE TO	O ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD INTERMEDIATI FLOWED FLOWED
5 minutes	Steady Flow
10 minutes	Surges_
15 minutes	Down to Nothing
20 minutes	Nothing X
25 minutes	Gas
30 minutes	Gas & Water
	Water 2009
If bradenhead flowed water, check all of the descriptions	that apply below:
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN BRADENHEAD	INTERMEDIATE
REMARKS: WELL SUM HOLE BRADEN HEAD CEMENTED TO SURFACE	
By Byclfl	Witness
Puncer (Position)	
E-mail address	