



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 1-13-05 Operator Elmridge Acs API #30-039-06677
Property Name CANDLER Well No. 12 Location: Unit Section 3 Township 26N Range 7W
Well Status (Shut-In or Producing) Tubing 141 Intermediate Casing ✓ Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>✓</u>	Steady Flow <u> </u>	
10 minutes	<u>0</u>		<u>✓</u>	Surges <u> </u>	
15 minutes	<u>0</u>		<u>✓</u>	Down to Nothing <u> </u>	
20 minutes	<u>0</u>		<u>✓</u>	Nothing <u> </u>	<u>X</u>
25 minutes	<u>0</u>		<u>✓</u>	Gas <u> </u>	
30 minutes	<u>0</u>		<u>✓</u>	Gas & Water <u> </u>	
				Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS: RIO ARRIBA CO. NM.

By [Signature]
(Position)

Witness

E-mail address

