

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of To	est / 13	-05 C	perator	In Ridge R	SAPI #30-0 <u>39</u> -	06742
Date of Test 1 - 13 - 0 5 Operator F m Rilipul RSAPI#30-039-06742 Property Name CARdy do Well No. 9 Location: Unit Section 3 Township 26 N Range 7W						
Well Status (Shut-In or Producing) Tubing producing Intermediate Casing Bradenhead D						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME		PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATI FLOWED
5 minutes_	0			Steady Flow		
10 minutes	0			Surges		
15 minutes	<u> </u>			Down to Nothin	ng	
20 minutes	0			Nothing	X	
25 minutes	00			Gas	/	
30 minutes	. 0			Gas & Water		
				Water		02122337
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK						
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE						
REMARKS: RIO ARRILA CO, NM,						
	<u> </u>				4254	CZ WEST
	,					
Ву	m Li	Jun shop		Witness		
(P	Cosition)	Bev	The state of the s			
E-mail address						