NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division Aztec District Office 1000 Rio Brazos Road Aztec, NM 87410 (505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	12-21-04	Operator	Dugan Production Corp.				ADI# 30-030-23076						
													0014
Property Name STRAWBERRY		Well No. 1 Locatio		•		<u> </u>	-		_Township		Range	06/	
Well Status(Shu	70 ^{ff} Intermediate				Casing 70			Bradenhead			_		
	OPEN BRADE	NHEAD AI	ND INTE	RMEDIAT	E TO A	тмоѕі		INDIVI	DUAL	LY FOR		JTES E	EACH
TIME	INTERMEDIATE	CASING					FLOWE			FLOWED			
5 mintues		70*	-	Steady Flow			D	-					
10 minutes		70#	-	Surges			-0-					_	
15 minutes	***	70#		Down to Noth	ning		0			M123	455	_	
20 minutes			- N	lothing				k	160°2.	./A.	0'1		
25 minutes		Gas				Se 0/ 2005					<u></u>		
30 minutes			Gas & Water										
	Water												
If bradenhead flowed water, check all of the descriptions that apply below:													
	CLEAR		FRESH_	<u></u>	SALTY		SULFU	R	BLAC	:к	_		
5 MINUTE S	SHUT-IN	BRADENHE	AD _	0	•	INTER	MEDIATE			_			
												- -	
Ву	BIDA	Switcher (Position)	<u>/</u>			Witnes	s					_	