



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12/25/04 Operator ELI ARIZOLA RES API #30-0 39-06312

Property Name Ticapiilla 118 A Well No. 1 Location: Unit A Section 26 Township 26N Range 3W

Well Status (Shut-In or Producing) Tubing 106 Intermediate N/A Casing 138 Bradenhead 138

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>60</u>	<u>N/A</u>	<u>60</u>
10 minutes	<u>25</u>	<u>N/A</u>	<u>25</u>
15 minutes	<u>5</u>	<u>N/A</u>	<u>5</u>
20 minutes	<u>5</u>	<u>1</u>	<u>5</u>
25 minutes	<u>5</u>	<u>1</u>	<u>5</u>
30 minutes	<u>5</u>	<u>1</u>	<u>5</u>

BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas ☒	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN BRADENHEAD 25 INTERMEDIATE N/A


REMARKS:

By Paul Chizman

Witness

Contract Pumper
(Position)

E-mail address



Letter to R. H. R.
1-24-05

DIG 9P