



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12/03/04 Operator CDX GAS LLC API # 3003906065
Property Name 112 Cont #146-1.6 Location: Unit M Section 10 Township 25N Range 5W
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing Ø Intermediate Ø Casing Ø Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	Ø	Ø				Steady Flow		
10 minutes						Surges		
15 minutes						Down to Nothing	✓	
20 minutes						No Flow		
25 minutes						Gas	✓	
30 minutes						Gas and Water		
5 minute SI	✓	✓				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____


REMARKS:

Both Csg. & BH had very little psi unable to move gauge
w/ reading.

Juice Montoya
Field Tech

Witness

(Position)



NMOCD Test Area: C