



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12/04/04 Operator CDX. GAS LLC API # 3003906561
Property Name JIC Apache 102-3 Location: N 44° 5W/4 Unit K Section 9 Township 26N Range 5W
(Well Name and Number)
Pressure (Shut-in or Producing) Tubing 60 Intermediate _____ Casing 60 Bradenhead 60

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>60</u>				☒	
10 minutes	<u>0</u>	<u>60</u>					
15 minutes	<u>0</u>	<u>60</u>				☒	
20 minutes	<u>0</u>	<u>60</u>					
25 minutes	<u>0</u>	<u>60</u>					
30 minutes	<u>0</u>	<u>60</u>				☒	
5 minute SI	<u>5</u>	<u>60</u>					

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

REMARKS:

BH blew down to a steady vent not enough to measure
on gauge. Build up to 5 lbs in 5 min SI

by Unice Montoya
Field tech
(Position)

Witness _____