



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 10/12/04 Operator CDX Gas API # 3003908097
Property Name Jicarilla A-7 Location: Unit Section 17 Township 26N Range 5W
(Well Name and Number)
Pressure (Shut-In) or Producing Tubing 101 Intermediate — Casing 47 Bradenhead 59

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	0	47				light blow						
10 minutes		47										
15 minutes		47										
20 minutes												
25 minutes												
30 minutes												
5 minute SI	7									X		

If bradenhead flowed water, check all of the descriptions that apply below:


Clear Fresh Salty Sulfur Black

EMARKS: Blew down in 1 minute but still has steady flow of gas TSTM

Duane Harrison
Field Tech

(Position)

Witness



NMOCD Test Area: C