

NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 10/13/04 Operator CDX API # 3003923697
Property Name Jic Cont 148#40 Location: Unit NE 1/4 NE 1/4 Section 13 Township 25N Range 5W
(Well Name and Number)
Pressure (Shut-in or Producing) 0 Tubing 0 Intermediate 0 Casing 895 Bradenhead 895

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor
5 minutes	0	895			
10 minutes	0	895			
15 minutes	0	895			
20 minutes					
25 minutes					
30 minutes					
5 minute SI	10	895			

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing	✓	
No Flow		
Gas	✓	
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:


Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

REMARKS:
Well TD master valve lock out - tag out SI. Blew down to 0 in 1 second.

Vince Montoya
Field Tech

(Position)

Witness _____



NMOCD Test Area: C