



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12/03/04 Operator CDX GAS LLC API # 3003923699
Property Name Jc Cont #148-40 Location: N44 W44 Unit A Section 13 Township 25N Range 5W
(Well Name and Number)
Pressure (Shut-in or Producing) _____ Tubing 1165 Intermediate _____ Casing 890 Bradenhead 860

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>890</u>					
10 minutes							
15 minutes							
20 minutes							
25 minutes							
30 minutes							
5 minute SI	<u>.5</u>	<u>890</u>					

Steady Flow _____
Surges _____
Down to Nothing ✓
No Flow _____
Gas ✓
Gas and Water _____
Water _____

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

REMARKS:

BH blew down in about 2 sec.

by Vince Montoya
Field Tech
(Position)

Witness _____