

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator  
**BURLINGTON**  
RESOURCES OIL & GAS COMPANY LP

3. Address & Phone No. of Operator  
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M  
2100' FSL, 990' FWL, Sec.22, T-28-N, R-13-W, NMPM

5. Lease Number  
NMNM-09979

6. If Indian, All. or  
Tribe Name

7. Unit Agreement Name

8. Well Name & Number  
Southeast Cha Cha #38

9. API Well No.  
30-045-24816

10. Field and Pool  
Basin Fruitland Coal/  
West Kutz Pictured Cliff

11. County and State  
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment

Type of Action

☐ Abandonment ☐ Change of Plans  
☐ Recompletion ☐ New Construction  
☐ Plugging Back ☐ Non-Routine Fracturing  
☐ Casing Repair ☐ Water Shut off  
☐ Altering Casing ☐ Conversion to Injection  
☒ Other -

13. Describe Proposed or Completed Operations

The subject well was recompleted to the Basin Fruitland Coal and the West Kutz Pictured Cliffs from the Cha Cha Gallup on 7-27-04. During the recompletion the casing was pressure tested to 3000 psi for 15 minutes after the lower zones were plugged and abandoned but before the well was perforated and fracture treated. (By testing to 3000 psi, we exceeded the 500 psi pressure test required for the temporary abandon status). Burlington Resources is working to receive approval from the Navajo Tribe to connect the well to a pipeline.

Please consider this well temporarily abandoned.

TA OK  
Expires 7-27-2006  
CP

14. I hereby certify that the foregoing is true and correct.

Signed Nancy Olthmann Title Senior Staff Specialist Date 2/2/05

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_  
CONDITION OF APPROVAL, if any: