



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrmd.state.nm.us/ocd/District/11/33distric.htm>

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 5-25-04 Operator DJ Simmon API # 30-039-27262
Property Name Byrne Well No. 24-1 Location: Unit Section 24 Township 25N Range 3W
Well Status (Shut-In or Producing) Tubing 0 Intermediate Casing 125 Bradenhead 125

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes			Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS:

Bradenhead valve and casing valve show
some pressure. did not flow bradenhead because
it is casing on this well

By [Signature]
Field Tech
(Position)

Witness