

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT


Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 5-19-04 Operator Dugan Production Corp. API # 30-039-22787  
Property Name BETTY C 31 Well No. 3 Location: Unit K Section 31 Township 24N Range 07W  
Well Status(Shut-In or Producing) \_\_\_\_\_ Tubing 5" Intermediate \_\_\_\_\_ Casing 5" Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>5"</u>	Steady Flow		
10 minutes		<u>5"</u>	Surges		
15 minutes		<u>5"</u>	Down to Nothing		
20 minutes			<u>Nothing</u>		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		



**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD Ø INTERMEDIATE \_\_\_\_\_

REMARKS:  
Nothing

By Bill Asmunda \_\_\_\_\_ Witness \_\_\_\_\_  
26 Switcher \_\_\_\_\_  
(Position)