

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-27-04 Operator Dugan Production Corp. API # 30-039-22894
Property Name DOME FED 34-24-7 Well No. 3 Location: Unit H Section 34 Township 24N Range 07W
Well Status(Shut-In or Producing) _____ Tubing 62 Intermediate _____ Casing 65 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>65⁺</u>	Steady Flow		
10 minutes		<u>65⁺</u>	Surges		
15 minutes		<u>65⁺</u>	Down to Nothing		
20 minutes			<u>Nothing</u>		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

By Bill Armenta Witness _____

32

Switcher

(Position)

