



AND NATURAL RESOURCES DEPARTMENT

NEW MEXICO DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-16-04 Operator C.D. Rio, LLC API # 3023920244

Property Name Jicarilla Gap Com 356 #1 Location: Unit M Section 2 Township 24 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 110 # Intermediate Casing 80 # Bradenhead 0 #

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH- Blowdown	Casing- Monitor	Intermediate- Monitor	Intermediate- Blowdown	Casing- Monitor							
5 minutes	<u>0 #</u>											
10 minutes												
15 minutes												
20 minutes												
25 minutes												
30 minutes												
5 minute St												

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur

5 Minute Shut-in Bradenhead 0 # Intermediate


REMARKS:

by Harry Whitson

Tech T.P.S

(Position)

Witness Darrell Spear T.P.S



NMOCD Test Area: