



AND NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-16-04 Operator CDX Rio, LLC API # 3003922170
Property Name Jicarilla Gas Com 35C #1E Location: Unit J Section 2 Township 24 Range 5
(Well Name and Number) #1E
Pressure (Shut-in or Producing) Tubing 75 Intermediate _____ Casing 75 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0 #</u>					Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing	
20 minutes						No Flow <u>X</u>	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute St						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead 0 # Intermediate _____

REMARKS:



by Harry Wilson
Tech T.P.S
(Position)

Witness Daniel Spier T.P.S

NMOCD Test Area: