

30-045-29251

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report



Name of Company: BP	Contact: Courtney Cochran
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 326-9457
Facility Name: Bolack E 1M	Facility Type: natural gas well
Surface Owner: Federal	Mineral Owner: Federal
Lease No. NM 012202	

LOCATION OF RELEASE

Unit Letter I	Section 33	Township T28N	Range R8W	Feet from the 1590	North/South Line South	Feet from the 1090	East/West Line East	County: San Juan
------------------	---------------	------------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------------

Latitude 36.61541 Longitude 107.68112

NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: approx. 340 Mcf of gas	Volume Recovered: no gas recovered
Source of Release: rupture disc on separator	Date and Hour of Occurrence: 8:00 AM on 09/05/10	Date and Hour of Discovery: 11:15 AM on 09/05/10
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
<p>If a Watercourse was Impacted, Describe Fully.*</p> <p style="text-align: right;">RCVD SEP 15 '10</p> <p style="text-align: right;">OIL CONS. DIV.</p> <p style="text-align: right;">DIST. 3</p>		
<p>Describe Cause of Problem and Remedial Action Taken.*</p> <p>The rupture disc on the L-PUD separator failed thereby allowing gas to escape to the atmosphere. The inlet to the separator was closed and the well shut in. The rupture disk and other equipment will be examined.</p>		
<p>Describe Area Affected and Cleanup Action Taken.*</p> <p>The gas released dissipated into the atmosphere so no clean-up action was possible.</p>		
<p>I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.</p>		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by District Supervisor:  For: CP	
Title: HSE Advisor	Approval Date: 9/21/10	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: September 13, 2010 9457	Phone: 326-	

* Attach Additional Sheets If Necessary

nBP1026432862