

A-PLUS WELL SERVICE, INC.**ORIGINAL
INVOICE**

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

July 7, 2004

New Mexico Oil Conservation Division

1 of 2

Aztec District

1000 Rio Brazos Road
Aztec, NM 87410

Invoice #3371
PO #04-199-000747



Rig #9

Horseshoe Gallup #72 Well

API #30-045-10803

Cost Summary:

ID#	Date	Item Description	Units	Unit Cost	Extension
Workover Rig, Travel and Supervision:					
A1	7/1/04	Contractors Supervisor / Cementer	0.5	\$ 250.00	\$ 125.00
A1	7/2/04	Contractors Supervisor / Cementer	1.0	\$ 250.00	\$ 250.00
A1	7/6/04	Contractors Supervisor / Cementer	0.5	\$ 250.00	\$ 125.00
A2	7/1/04	Crew travel, one way	1.5	\$ 112.00	\$ 168.00
A2	7/2/04	Crew travel, round trip	3.0	\$ 112.00	\$ 336.00
A2	7/6/04	Crew travel, one way	1.5	\$ 112.00	\$ 168.00
A3	7/1/04	Shallow Rig	4.75	\$ 140.00	\$ 665.00
A3	7/2/04	Shallow Rig	7.75	\$ 140.00	\$ 1,085.00
A3	7/6/04	Shallow Rig	3.75	\$ 140.00	\$ 525.00
Cementing Services:					
B1	7/1/04	Cementing equipment on location	0.5	\$ 450.00	\$ 225.00
B1	7/2/04	Cementing equipment on location	1.0	\$ 450.00	\$ 450.00
B1	7/6/04	Cementing equipment on location	0.5	\$ 450.00	\$ 225.00
B3	7/2/04	Cement, 95 sxs Type III = 106.3 sxs Type II	106.3	\$ 10.50	\$ 1,116.15
B3	7/6/04	Cement, set marker, 10 sxs III = 13.2 sxs Type II	13.2	\$ 10.50	\$ 138.60
Wireline Services:					
C1	7/2/04	Wireline unit on location, used	1.0	\$ 250.00	\$ 250.00
C3	7/2/04	Perforate up top 3 squeeze holes at 163'	1.0	\$ 300.00	\$ 300.00
Packers, Retainers & Casing Scrapers:					
D3	7/2/04	Cement retainer, tubing set, 5-1/2"	1.0	\$ 900.00	\$ 900.00
D4	7/2/04	Casing scraper rental, 5-1/2"	1.0	\$ 250.00	\$ 250.00
Workstrings & Miscellaneous Rentals:					
E1.1	7/2/04	Workstring rental, 2-3/8", feet	1303	\$ 0.12	\$ 156.36
E6.3	7/2/04	Companion flange rental, 5-1/2"	1.0	\$ 50.00	\$ 50.00
E7.1	7/2/04	Tubing Head for 5-1/2" casing	1.0	\$ 100.00	\$ 100.00
E14	7/6/04	Waste fluid container, days used	2.0	\$ 30.00	\$ 60.00

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

**ORIGINAL
INVOICE**

July 7, 2004

2 of 2

New Mexico Oil Conservation Division**Aztec District**

1000 Rio Brazos Road
Aztec, NM 87410

Invoice #3371
PO #04-199-000747

Rig #9

Horseshoe Gallup #72 Well
API #30-045-10803

Transportation and Miscellaneous Services:

			\$	-
			\$	-
F1.a	7/1/04 Unit #141, Haul workstring & pit to loc.	2.0	\$74.00	\$ 148.00
F1.b	7/2/04 Unit #141, Move workstring into position;	2.0	\$74.00	\$ 148.00
F1.c	7/16/04 Unit #152, Haul waste pit to IEL landfarm, unload;	1.0	\$74.00	\$ 74.00
F2.d	7/16/04 Helper for above	1.0	\$20.00	\$ 20.00
F4	7/1/04 Float #98, rental, carry workstring;	2.0	\$15.00	\$ 30.00
F6.a	7/1/04 Unit #134, Haul 1 load of water to location	2.0	\$50.00	\$ 100.00
F6.b	7/2/04 Unit #134, Haul 1 load of water to location	2.0	\$50.00	\$ 100.00
F6.c	7/1/04 Unit #155, Haul waste fluid to location;	2.0	\$50.00	\$ 100.00
F6.d	7/2/04 Unit #155, Receive waste fluid, then hold	2.0	\$50.00	\$ 100.00
F7.a	6/2/04 Backhoe, Road repair - very dusty & rough;	12.5	\$50.00	\$ 625.00
F7.b	7/15/04 Backhoe, Clean up location, remove trash & junk;	3.0	\$50.00	\$ 150.00
F2.b	7/15/04 Helper for above	3.0	\$20.00	\$ 60.00
F11	7/6/04 P&A Marker	1.00	\$ 120.00	\$ 120.00

Third Party Charges:

G1	7/16/04 IEL landfarm, Inv #01819, take solid waste	1.00	\$18.00	
	Third Party Handling Charge - 8%	0.08	\$1.44	\$19.44

Salvage Credit:

S1	None, no tubing in well			N/A
----	-------------------------	--	--	-----

TOTAL \$ 9,462.55
TAX 6.3750% \$ 603.24

THANK YOU**TOTAL DUE \$ 10,065.79**

OK For Payment
Charlie Herrin
9-13-04

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Sundry Notices and Reports on Wells

COPY

1. **Type of Well**
Oil Well

2. **Name of Operator**
Central Resources, Inc. c/o NMOCD Aztec District Office

3. **Address & Phone No. of Operator**
1000 Rio Brazos Road, Aztec, NM 87410 505-334-6178

Location of Well, Footage, Sec., T, R, M

1854' FNL and 2108' FEL, Section 14, T31N, R17W,

5. **Lease Number**
BIA #14-20-603-2022

6. **If Indian, All. or Tribe Name**
Navajo

7. **Unit Agreement Name**
Horseshoe Gallup Unit

8. **Well Name & Number**
HSGU #72

9. **API Well No.**
30-045-10803

10. **Field and Pool**
Horseshoe Gallup Unit

11. **County & State**
San Juan County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

A-Plus Well Service Plugged and Abandoned the above well NMSA 1978, Section 13-1-127, Purchase Agreement: 04-521-0700028; Purchase Document: 04-199-000747.

7/1/04 MOL and RU. Open well. No pressure. NU BOP, test. Shut in well. SDFD.

7/2/04 No pressure. PU 41 joints A+ workstring and round-trip 5-1/2" casing scraper to 1303'. TIH with tubing and set 5-1/2" DHS cement retainer at 1303'. Sting out of retainer. Load the casing with 12 bbls of water. Pump additional 19 bbls of water to circulate well clean. Pressure test casing to 500# for 5 minutes, Held OK. Sting into retainer and pump fluid from pit below retainer, displace. Sting out of retainer. Plug #1 with CR at 1303', spot 41 sxs Type III cement (54 cf) inside casing above CR up to 908' to isolate the Gallup interval. TOH and LD tubing. Perforate squeeze holes at 163'. Establish circulation out bradenhead with 6 bbls of water. Pump additional 15 bbls of water to circulate BH annulus clean. Plug #2 with 54 sxs Type III cement (71 cf) pump down the 5-1/2" casing from 163' to surface, circulate good cement out bradenhead. Shut in well and SDFD.

7/6/04 ND BOP. Dig out and cut off wellhead. Found cement down 10' in casing and at surface in annulus. Mix 10 sxs Type III cement (13 cf) to fill casing and install P&A marker. RD and MOL.

H. Villanueva, NMOCD was on location.

SIGNATURE William F. Clark Contractor

July 31, 2004

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

22676

Rig No. #9

Date 07/01/04 Day THU

Well Name HORSESHOE GALLUP UNIT # 72 Company PLAYA MINERALS & ENERGY

[illegible]

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing _____

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	MIKE HILDON	#21		
Operator	TRAVIS BECAV	#19		6.25
Helper	LORENZO RODRIGUEZ			6.25
Helper	ADAN REYES			6.25
Helper	CHRIS MONTANEZ			6.25
Trainee				

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

22677

Rig No #9Date 07/02/04 Day FRIWell Name HORSESHOE GALLUP UNIT #72 Company PLAYA MINERALS & ENERGY

1 1/2 hr

FROM	TO	DESCRIPTION OF OPERATION
5:30	5:45	LOAD RIG SUPPLIES
5:45	7:15	TRAVEL TO LOCATION
7:15	7:45	START RIG AND EQUIPMENT. HELD PRE-SUB SAFETY MEETING
7:45		OPEN WELL (NO PRESSURE)
		PICK UP AND TIEH/ 5 1/2" CSG SCRAPER AND 41 JTS - 2 3/8" A-PLUS
	9:00	WORK STRING. EOT @ 1303'
9:00	9:45	TOH/ TBG AND SCRAPER.
9:45	10:45	TIEH/ 5 1/2" DHS CRT AND TBG. SET CRT @ 1303'. STING OUT OF CRT.
10:45		LOAD HOLE/ 12 BBLs TO CIRCULATE. CIRCULATE HOLE CLEAN/AN
		ADDITIONAL 19 BBLs WATER. PRESSURE TEST CSG TO 500PSI.
	11:15	HELD PRESSURE 5 MIN. NO PRESSURE LOSS. BLED PRESSURE OFF.
11:15		STING INTO CRT. INJECT FLUID FROM PIT BELOW CRT. DISPLACE.
	12:45	STING OUT OF CRT.
12:45		PLUG #1 - MIX AND PUMP 41 SXS TYPE III 14.5" CMT FROM 1303' TO
	1:15	TOL @ 908'. DISPLACE.
1:15	2:00	LAY DOWN TBG AND STINGER.
2:00		RIG UP WIRELINE. RIH/ WIRELINE. PERFORATE WITH 2- 1 1/16" BI-WIRE
	2:30	SHOTS @ 163'. POH/ WIRELINE. RIG DOWN WIRELINE.
2:30		PUMP 6 BBLs WATER DOWN CSG TO CIRCULATE OUT BRADENHEAD.
		CIRCULATE CLEAN/AN ADDITIONAL 9 BBLs. STILL CIRCULATING SOME
		OIL OUT BRADENHEAD. WAIT 15 MIN. PUMP 3 BBLs AND CIRCULATED
		3 BBLs OIL OUT BH. WAIT 20 MIN. PUMP 3 BBLs WATER AND CIRCULATED
	3:30	2 BBLs OIL OUT BRADEN HEAD.
3:30		PLUG #2 - MIX AND PUMP 54 SXS TYPE III 14.6" CMT DOWN CSG TO
		CIRCULATE GOOD CMT OUT BRADEN HEAD.
	4:00	SECURE WELL.
4:00	5:30	TRAVEL TO YARD.
		HENRY VILLANUEVA/ NMOLD ON LOCATION

7 3/4 hr

1 1/2 hr

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers 5 1/2" DHS @ 1303'Cementing PLUG #1 - 41 SXS TYPE III PLUG #2 - 54 SXS TYPE IIIWireline 2- 1 1/16" BI-WIRE @ 163' (MH)

One Day

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	MIKE HILDON	#21		
Operator	TRAVIS BEGAY #221 IN AND FILL	#19		13.0
Helper	ADAN REYES			12.0
Helper	CHRIS MONTANEZ			12.0
Helper	GORDON NACKETT			12.0
Trainee				

22679

Rig No. #9

Date 07/06/09 Day TUE

Well Name NURSESHOE GALLUP UNIT # 72

Company PLAYN MINERALS & ENERGY

[illegible]

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing P+A MARKER / 10 SKS

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	MIKE HIGDON	#21		
Operator	TRAVIS BELAY	#19		6.05.5
Helper	LORENZO RODRIGUEZ			6.05.5
Helper	ADAN REYES			6.05.5
Helper	CHRIS MONTANEZ			6.05.5
Trainee				

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

6277

Date: _____

Truck #: 141

Event: #1	From: HGU #77	To: HGU #72	Hours
Start:	What: HAUL FLGAT #98 AND PIT #525		
7/01/09			
Stop:	Charge to: NMUCD		2.0
Event: #2	From: HGU #72	To:	
Start:	What: STANDBY		
7/02/09			
Stop:	Charge to: NMUCD		2.0
Event: #3	From: HGU #72	To:	
Start:	What: STANDBY		
7/06/09			
Stop:	Charge to: NMUCD		2.0
Event: #4	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #5	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #6	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #7	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	
Start:	What:		
Stop:	Charge to:		
	Driver: MIKE HIGDON		4.0
Diesel:	Helper		
Oil:	NM MILES: _____ CO MILES: _____ UT MILES: _____		
Remarks:			

F1.2

F1.6

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

6301

Date: 7-16-04

Truck #: 24

Event: #1	From: A-P-W	To: CARGO PIPE YARD	Hours
Start: 10:30	What: HOOK UP TO UNIT 87 & GO TO CARGO		
	5 UNLOAD PIPE & DRIVE BACK TO YARD		1.5
Stop: 12:00	Charge to: NMOC		
Event: #2	From: A-P-W	To: HSCU # 80	
Start: 12:00	What: DRIVE TO LOCATION & LOAD PIT		1
Stop: 2:00	Charge to: NMOC		
Event: #3	From: HSCU # 80	To: IEI	
Start: 2:00	What: DRIVE TO IEI & EMPTY OUT PIT		1
Stop: 4:00	Charge to: NMOC		
Event: #4	From: IEI	To: A-P-W	
Start: 4:00	What: LOAD PIT & CHAIN DOWN & DRIVE TO YARD		1
Stop: 5:00	Charge to: NMOC		
Event: #5	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #6	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #7	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	
Start:	What:		
Stop:	Charge to:		
	Driver: DUANE GUSTIN		6.5
Diesel:	Helper: FLOYD BOGAY		6.5
Oil:	NM MILES: 28	CO MILES: _____	UT MILES: _____
Remarks:	46-HWY + 32 DIRT		
	I BROKE FITTINGS OFF THE BACK SIDE OF PIT		
	NMOC HSCU #80, 82, 74, 77		
	load pit and haul to IEI for disposal		

Sho

F.I.C

1 hr each

F2.6

Helper 5 hrs.

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

6278

Date: _____

Truck #: 134

Event: #1	From: HGU #77	To: HGU #72	Hours
Start:	What: STANDBY		
7/01/09			
Stop:	Charge to: NMOC D		2.0
Event: #2	From: HGU #72	To:	
Start:	What: HAUL 2 LOADS AND STANDBY		
7/02/09			
Stop:	Charge to: NMOC D		2.0
Event: #3	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #4	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #5	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #6	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #7	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	
Start:	What:		
Stop:	Charge to:		
	Driver: MIKE HIGDON		4.0
Diesel:	Helper		
Oil:	NM MILES: _____ CO MILES: _____ UT MILES: _____		
Remarks:			

F6.2

F6.6

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

6285

Date: _____

Truck #: 155

Event: #1	From: HGU #77	To: HGU #72	Hours
Start:	What: STANDBY FOR DISPOSAL		
07/01/09			
Stop:	Charge to: NMOCID		2.0
Event: #2	From: *HGU #72	To:	
Start:	What: STANDBY FOR DISPOSAL		
07/02/09			
Stop:	Charge to: NMOCID		2.0
Event: #3	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #4	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #5	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #6	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #7	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	
Start:	What:		
Stop:	Charge to:		
	Driver: MIKE HIGDON		4.0
Diesel:	Helper		
Oil:	NM MILES: _____ CO MILES: _____ UT MILES: _____		
Remarks:			

F6.C
F6.d

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

6170

Date: 6-02-04

Truck #: 34

Event: #1	From: A-P-W	To: HSG CAVE	Hours
Start: 5:30	What: PRE TRIP UNIT 34 & 85		
Stop: 6:00	Charge to: NMOCO		1.5
Event: #2	From: A-P-W	To: CAVE	
Start: 6:00	What: DRIVE TO CAVE, & ILLINOIS PIPE, & DRIVE BACK TO A-P-W		2
Stop: 8:00	Charge to: NMOCO		
Event: #3	From: A-P-W	To: HSG 77	
Start: 8:00	What:		1.5
Stop: 9:30	Charge to: NMOCO		
Event: #4	From: HSG 77	To:	
Start: 9:30	What: BUILD ROAD INTO THE 77		1.7
Stop: 4:30	Charge to: NMOCO		
Event: #5	From: HSG 77	To: A-P-W	
Start: 4:30	What: DRIVE TO YARD		1.5
Stop: 6:00	Charge to: NMOCO		
Event: #6	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #7	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	
Start:	What:		
Stop:	Charge to:		
	Driver: DANN GUSTIN		12.5
Diesel:	Helper		
Oil:	NM MILES: 54 (40) CO MILES: UT MILES:		
Remarks:	230127		
	NMOCO HSGU #77		
	Build Road into location		

12.5 hrs.

F7.7

12 1/2 hrs

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

6249

Date: 7-15-04

Truck #: 24

Event: #1	From: A-P-W	To: NSGU # 77	Hours
Start: 5:30	What: CLEAN LOCATION & REMOVE TRASH & RISERS		
Stop: 8:30	Charge to: NMOC		3
Event: #2	From: NSGU # 72	To:	
Start: 8:30	What: CLEAN LOCATION & REMOVE TRASH & RISERS		3
Stop: 11:30	Charge to: NMOC		
Event: #3	From: NSGU # 74	To:	
Start: 11:30	What: CLEAN LOCATION & REMOVE TRASH & RISERS		3
Stop: 2:30	Charge to:		
Event: #4	From: NSGU # 82	To:	
Start: 2:30	What: CLEAN LOCATION & REMOVE TRASH & RISERS		3
Stop: 5:30	Charge to:		
Event: #5	From: NSGU # 79	To:	
Start: 5:30	What: FIX ROAD IN TO LOCATION		.75
Stop: 6:15	Charge to:		
Event: #6	From: NSGU # 93	To:	
Start: 6:15	What: FIX ROAD INTO LOCATION		.75
Stop: 7:15	Charge to:		
Event: #7	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	
Start:	What:		
Stop:	Charge to:		
	Driver: DUNN GUSTIN		13.5
Diesel: P/A	Helper FLOYD BOGAY		13.5
Oil:	NM MILES: 78	CO MILES: _____	UT MILES: _____
Remarks:	46 HWY + 32 DIRT = 78		
	NMOC NSGU # 72		
	Clean location + remove trash + risers		

3 hrs.

F7.6

3 hrs.

F2.6

Helper 3 hrs.



JUL 31 2004

Invoice Number: 4234
Invoice Date: Jul 28, 2004
Page: 1

Industrial Ecosystems Inc.

P.O. Box 2043

Farmington, NM 87499

PH: (505) 632-1782 Fax: (505) 632-1876

TAX I.D. #94-3200034

PLEASE REMIT PAYMENT TO:

Industrial Ecosystems, Inc.

c/o John J. Kiely

401 S. Lasalle St., Suite 606

Chicago, Illinois 60605

Sold To: A PLUS WELL SERVICE
PO BOX 1979
FARMINGTON, NM 87499

Location: BILL CLARK
HSGU#72

Contact	Payment Terms	Due Date	Customer PO
BILL CLARK	Net 30 Days	8/27/04	

Quantity	Description	Unit Price	Extension
1.00	DATE OF SERVICE: 07/16/04 MATERIAL TRANSPORTED BY: APLUS - TRUCK#152 DISPOSED OF CONTAMINATED SOIL DISPOSAL FEE PER YARD	90.00	90.00
61-1.1			

FOR BILLING INQUIRIES PLEASE CALL
(505) 632-1782

ACCOUNTS ARE DUE NET 30 DAYS. PURCHASER AGREES TO PAY
FINANCE CHARGES OF 1.5% PER MONTH (ANNUAL PERCENTAGE RATE
OF 18%) OR A MINIMUM CHARGE OF .50 PER MONTH. ACCOUNTS THAT
HAVE BEEN PLACED FOR COLLECTION WILL BE CHARGED A \$100.00
COLLECTION FEE IN ADDITION TO REASONABLE ATTORNEY FEES AND
COLLECTION CHARGES.

Subtotal	90.00
Sales Tax	
Total Invoice Amount	90.00
TOTAL	90.00



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor

Betty Rivera
Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

CERTIFICATE OF WASTE STATUS

1. Generator Name and Address Central Resources, Inc. c/o NMOCD - Charlie Perrin A-Plus Well Service, Inc. Plugging Contractor to NMOCD	2. Destination Name: J.F.J. Landfarm c/o Industrial Ecosystems Inc. 420 CR 3100 Aztec, NM 87410
3. Originating Site (name): HSGU #72 HSGU #74 HSGU #82	Location of the Waste (Street address &/or ULSTR): Section 14, T31N, R17W, San Juan County, NM Section 14, T31N, R17W, San Juan County, NM Section 13, T31N, R17W, San Juan County, NM
attach list of originating sites as appropriate	
4. Source and Description of Waste Cement waste, sediments and fluid from plugging operations.	
5.	

I, Linda G. Clark representative for :
Print Name

A-Plus Well Service Inc. do hereby certify that, according to the
Resource Conservation and Recovery Act (RCRA) and Environmental Protection Agency's July, 1988, regulatory determination, the
above described waste is: (Check appropriate classification)

☒ **EXEMPT** oilfield waste ☐ **NON-EXEMPT** oilfield waste which is non-hazardous by characteristic
analysis or by product identification

and that nothing has been added to the exempt or non-exempt non-hazardous waste defined above.

For **NON-EXEMPT** waste the following documentation is attached (check appropriate items):

☐ MSDS Information ☐ Other (description)
☐ RCRA Hazardous Waste Analysis
☐ Chain of Custody

This waste is in compliance with Regulated Levels of Naturally Occurring Radioactive Material (NORM) pursuant to 20
NMAC 3.1 subpart 1403.C and D.

Name (Original Signature): Linda G. Clark

Title: _____

Date: 7/16/04