

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary

Brett F. Woods, Ph.D.
Deputy Cabinet Secretary

David R. Catanach, Division Director
Oil Conservation Division



December 7, 2015

Certified Mail

Return Receipt#: 7013 1090 0001 7318 3992

Lori Notor
ConocoPhillips Company
3401 E. 30th Street
Farmington, NM 87402

Re: Well Name Newsom #2, UL M Sec 17 Twn 26N Rge 8W,
API # 30-045-05825

Dear Ms. Notor:

The 2015 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before **February 4, 2016**. Initial Surface Casing psi was 18. Initial Production Casing psi was 117.

The Gas analysis and wellbore schematic have been received. Gas analysis show same gas on bradenhead and production casing.

A plan of action was received on October 5, 2015.

Reference: RBDMS MPK1533832694 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 116.

Sincerely yours,

Brandon Powell
Deputy Oil and Gas Inspector
District III - Aztec
CC: Well File