



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emurad.state.nm.us/ocd/District/3/district.htm>

OIL CONS. DIV DIST. 3

JAN 20 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1/20/2017 Operator Synergy API #30-045-33427

Property Name Duff 2118 Well No. 105 Location: Unit L Section 8 Township 29 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 53 Intermediate NA Casing 52 Bradenhead -0.7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		52		
10 min	0		52		
15 min	0		52		
20 min	0		52		
25 min	0		52		
30 min	0		51		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

BH through 1" valve, repressure on BH, no flow. Nothing when opened at start of test and following 5 min shut in.

By Thomas E. Mullins
(Position)

Witness Janet D. Kelly

E-mail address Tom.mullins@SYNERGYOPERATING.COM