

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 1-22-2020 Operator				r Logos	Logos Operating, LLC			API# 3004506621	
Property Name RICHARDSON 002 (Well Name and Number)				Location: Unit P Section 11 Township 27 Range 13					
Pressure (Shut-in or Producing) Tubing N/A Intermediate N/A Casing O Bradenhead 17									
OPEN	BRADENH	EAD AND	INTERMEDIA	ATE TO ATMOSI	PHERE IND	IVIDUALLY FOR	15 MINUTES E	ACH	
		Bradenhead BH Casing Intermediate			Intermediate		Bradenhead Intermediate		
<u>Time</u>	Blowdown	Monitor	Monitor	Blowdown	Monitor		Flowed	Flowed	
5 minutes	0	0				Steady Flow			
10 minutes	0	0				Surges			
15 minutes	0					Down to Nothing			
20 minutes	0	0				No Flow			
25 minutes		0				Gas	V		
30 minutes		0				Gas and Water			
	_0	0				Water			
5 minute SI	0								
If bradenhead flowed water, check all of the descriptions that apply below:									
Clear Fresh Salty Sulfur Black									
5 Minute Shut-in Bradenhead 200 Intermediate <u>NA</u>									
REMARKS:	ard Put	of wh	ien BH a	pen.					
By Engla	ne Bu	rbæn	k	Wi	tness /	Nombe The	ching		
11000	uchon	Voces	Han						
		(Position	1)						