



**NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 1-22-2020 Operator Logos Operating, LLC API # 3004534426

Property Name CENTRAL BASIN SWD 001 Location: Unit N Section 9 Township 28 Range 13
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 356 Intermediate N/A Casing -9 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	<u>0</u>	<u>-9.0</u>				Steady Flow	
10 minutes	<u>0</u>	<u>-9</u>				Surges	
15 minutes	<u>0</u>	<u>-9</u>				Down to Nothing	☒
20 minutes						No Flow	
25 minutes						Gas	☒
30 minutes						Gas and Water	
5 minute SI	<u>0</u>					Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear ☐ Fresh ☐ Salty ☐ Sulfur ☐ Black ☐

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

Puff when opened. 5 min shut in had light Puff through
1/4 in" ~~needle valve~~ ~~valve~~ needle valve.

By Eugene Burbank
Production Foreman
(Position)

Witness Mona Kuehling