



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

OCD Received
5/22/2020

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 5-19-20 Operator Logos Operating, LLC API # 3004535241

Property Name RICHARDSON 103 Location: Unit L Section 1 Township 27 Range 13
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 3 Intermediate N/A Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>30</u>				Steady Flow	<u>N/A</u>
10 minutes	<u>0</u>	<u>30</u>				Surges	
15 minutes	<u>0</u>	<u>30</u>				Down to Nothing	
20 minutes						No Flow	<u>X</u>
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	<u>0</u>	<u>30</u>				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By Justin Martinez [Signature] Witness _____
Lease Operator
(Position)