

NEW MEXICO ENERGY, MINIERALS. & NATURAL RESOURCES DEPARTMENT

OR. CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RID BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX; (505) 334-6170
http://emnrd.state.nm.us/ocd/District inv3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/14/2020 Operator 5	and Juan Res. API #30-045-28857
Property Name Beam HALL Well No. 2 Location: Unit A Section 18 Township 30 Range 11 W	
Well Status Shut-In or Producing) Initial PSI: Tubing / Intermediate // Casing // Bradenhead /	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 0 12.3 MA	Steady Flow
10 min Ø 14./	Surges
15 min Ø 17.8	Down to Nothing
20 min	Nothing X
25 min	Gas
30 min	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD D INTERMEDIATE MA	
REMARKS:	
By Arldy Prada Witness_	
Pomple. (Position)	
E-mail address ANDY WALS GAL WET	