



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OCD Received
6/17/2020

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrmd.state.nm.us/oed/District/IV3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/15/20 Operator SAN JUAN RES. API #30-0 45-29139
Property Name FLORA VISTA Well No. 19-2 Location: Unit N Section 19 Township 30^N Range 11^W
Well Status (Shut-In) or Producing Initial PSI: Tubing 5 Intermediate 0 Casing 7 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		7.1		
10 min	0		7.3		
15 min	0		7.6		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

By Andy Prada
Pumper
(Position)

Witness _____

E-mail address _____