



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OCD Received
6/17/2020

OH. CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District IV3/district.htm](http://emnr.state.nm.us/ocd/District%20IV3/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/18/20 Operator SAN JUAN RES. API #30-0 45-30803

Property Name LEE Well No. 1E Location: Unit F Section 30 Township 30N Range 11W

Well Status (Shut-In) or Producing Initial PSI: Tubing 17 Intermediate 1 Casing 66 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	Ø	1	66	Ø	66
10 min	Ø	1	66	Ø	66
15 min	Ø	1	66	Ø	66
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X -
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE Ø

REMARKS:

pumped well Intermediate blew down in 15 seconds.

By Andy Prada
(Position) PUMPER

Witness _____

E-mail address _____