



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

NMOC

AUG 07 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/10/19 Operator Enduring Resources LLC API #30-039-06918
Property Name Rincon Unit Well No. 127 Location: Unit _____ Section _____ Township _____ Range _____
Well Status (Shut-In or Producing) Initial PSI: Tubing 74 Intermediate 211 Casing 79 Bradenhead 9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	Ø	211	80	22	68
10 min	Ø	211	81	Ø	63
15 min	Ø	211	81	Ø	60
20 min	Ø	211	82	Ø	57
25 min				Ø	55
30 min				Ø	53

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 9 INTERMEDIATE Ø

REMARKS:

- bradenhead down to vapors in one second; bradenhead had vapor to 20 min.
- not blown down prior to test per request
- intermediate down to vapor after 10; down to nothing at 25

By John Dockter

Witness Monica Kuehling

HSE Tech
(Position)

E-mail address JDockter@EnduringResources.com

- small flow after 5 minute intermediate, request gas sample

7/29/19