RECEIVED

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JUL 28 2011

Sundry Notices and Reports on Wells	<u>arming</u> :on Field Office ∋ureau of Land Managemen≀
1. Type of Well	5. Lease Number SF-079527 6. If Indian, All. or
2. Name of Operator RECE	Tribe Name 7. Unit Agreement Name San Juan 27-4 Unit
BURLINGTON RESCURCES OIL & GAS COMPANY LP 3. Address & Phone No. of Operator	2011 8. Well Name & Number San Juan 27-4 Unit 135M
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	61 ELL SHAPE 9. API Well No.
4. Location of Well, Footage, Sec., T, R, M Surface: Unit G (SENE), 1942' FNL & 1590' FEL, Section 36, T27N, R4	30-039-31039 10. Field and Pool
BH: Unit J (NWSE), 2150' FSL, & 1725' FEL, Section 36, T27N, R4W, NI	
Recompletion New Co X Subsequent Report Plugging Non-Ro Casing Repair Water S	d ahead to 236'. Circ hole. TIH w/ 7 jts., 9 5/8", s FW spacer. Pumped 76 sx (122cf-22bbls=1.60 yld)
PT will be conducted by Drilling Rig. Results will appear on next report APD/ROW	
14. I hereby certify that the foregoing is true and correct. Signed Denise Journey Times Tourney	tle:Regulatory Technician Date 7/28/11
(This space for Federal or State Office use) APPROVED BY	Date
the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction	ACCEPTED FOR RECORD
	JUL 2 9 2011
	FARMINGTON FIELD OFFICE BYS C

RU