District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd , Aztec, NM 87410

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

For temporary pits, closed-loop sytems, and below-grade tanks, submit to the appropriate NMOCD District Office.

Form C-144

July 21, 2008

For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office

Pit, Closed-Loop System, Below-Grade Tank, or Proposed Alternative Method Permit or Closure Plan Application Type of action: Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method Modification to an existing permit Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system, below-grade tank, or proposed alternative method

Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request

Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the invironment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinance.

environment Nor does approval relieve the operator of its responsibility to comply with any othe	r applicable governmental authority's rules, regulations or ordinances
Operator: Burlington Resources Oil & Gas Company, LP	OGRID#: 14538
Address: P.O. Box 4289, Farmington, NM 87499	
Facility or well name: REESE MESA 7H	
API Number: 30-045-35135 OCD Per	mit Number:
U/L or Qtr/Qtr: I(NE/SE) Section: 10 Township: 32N Rar	ge: 8W County: SAN JUAN
	ude: 107.65681 °W NAD: 1927 X 1983
Surface Owner: X Federal State Private Tribal Trus	et or Indian Allotment
X String-Reinforced	DPE HDPE PVC Other
Liner Seams: X Welded X Factory Other Volume	e: <u>7700</u> bbl Dimensions L <u>120'</u> x W <u>55'</u> x D <u>12'</u>
Closed-loop System: Subsection H of 19.15 17.11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling notice of intent)	(Applies to activaties which require prior approval of a permit or
Drying Pad Above Ground Steel Tanks Haul-off Bins Other Lined Unlined Liner type: Thickness mil LL Liner Seams: Welded Factory Other	DPE HDPE PVD Other 2345678970
Below-grade tank: Subsection I of 19.15.17.11 NMAC Volume: bbl Type of fluid: Tank Construction material: Secondary containment with leak detection Visible sidewalls, liner, 6-inch logical Visible sidewalls and liner Visible sidewalls only Other Liner Type: Thicknessmil HDPE PVC	Applies to activities which require prior approval of a permit or DPE HDPE PVD Other OIL CONS. DIV. DIST. 3 Other Other
Submittal of an exception request is required. Exceptions must be submitted to the Santa	

Form C-144

Oil Conservation Division

Page 1 of 5

6 Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pit, temporary pits, and below-grade tanks)					
Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, hospital, institution or church)					
Four foot height, four strands of barbed wire evenly spaced between one and four feet Alternate. Please specify		·			
Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)					
Screen Netting Other					
Monthly inspections (If netting or screening is not physically feasible)					
8 Signs: Subsection C of 19.15.17.11 NMAC					
12" X 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers	•				
X Signed in compliance with 19.15.3.103 NMAC					
9					
Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15 17 NMAC for guidance.					
Please check a box if one or more of the following is requested, if not leave blank:					
Administrative approval(s): Requests must be submitted to the appropriate division district of the Santa Fe Environmental Bureau office for consideration (Fencing/BGT Liner)	eration of appr	oval.			
Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.					
10					
Siting Criteria (regarding permitting) 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptable source material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau Office for consideration of approval. Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drying pads or above grade-tanks associated with a closed-loop system.					
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes	□No			
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	Yes	□No			
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.	Yes	No			
(Applies to temporary, emergency, or cavitation pits and below-grade tanks)	□NA				
- Visual inspection (certification) of the proposed site; Aerial photo; Satellite image					
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.	∐Yes	∐No			
(Applied to permanent pits) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	∐NA				
Within 500 horizonal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application.	Yes	□No			
- NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site.					
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended	Yes	□No			
- Written confirmation or verification from the municipality: Written approval obtained from the municipality Within 500 feet of a wetland.	Yes	□No			
- US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Within the area overlying a subsurface mine.	Yes	□No			
- Written confirmation or verification or map from the NM EMNRD - Mining and Mineral Division	∏Yes	□No			
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	LJ 'es				
Within a 100-year floodplain - FEMA map	Yes	□No			

Form C-144 Oil Conservation Division Page 2 of 5

Temporary Pits, Emergency Pits and Below-grade Tanks Permit Application Attachment Checklist Subsection B of 19.15.17.9 NMAC					
Instructions. Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.					
Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC					
Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9					
Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC					
Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC					
Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC					
Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC					
Previously Approved Design (attach copy of design) API or Permit					
Closed-loop Systems Permit Application Attachment Checklist:Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application Please indicate, by a check mark in the box, that the documents are attached. Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19 15.17.9					
Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC					
Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC					
Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC					
Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC					
Previously Approved Design (attach copy of design) API					
Previously Approved Operating and Maintenance Plan API					
13					
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC					
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.					
Hydrogeologic Report - based upon the requirements of Paragraph (I) of Subsection B of 19.15.17 9 NMAC					
Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17 10 NMAC					
Climatological Factors Assessment					
Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC					
Dike Protection and Structural Integrity Design based upon the appropriate requirements of 19.15.17.11 NMAC					
Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC					
Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC					
Quality Control/Quality Assurance Construction and Installation Plan					
Operating and Maintenance Plan - based upon the appropriate requirements of 19 15.17.12 NMAC					
Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H2S, Prevention Plan					
Emergency Response Plan					
Oil Field Waste Stream Characterization					
Monitoring and Inspection Plan					
Erosion Control Plan					
Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15 17.13 NMAC					
14					
Proposed Closure: 19.15.17 13 NMAC					
Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.					
Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System Alternative					
Proposed Closure Method: Waste Excavation and Removal					
Waste Removal (Closed-loop systems only)					
On-site Closure Method (only for temporary pits and closed-loop systems)					
In-place Burial On-site Trench					
Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)					
Waste Excavation and Removal Closure Plan Checklist (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan.					
Please indicate, by a check mark in the box, that the documents are attached.					
Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC					
Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC					
☐ Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) ☐ Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC					
Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC					
Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC					
Site Accordingtion From - oased upon the appropriate requirements of subsection of 17.13.17.13 INMAC					

Form C-144 Oil Conservation Division Page 3 of 5

16 Waste Removal Closure For Closed-loop Systems That Utilize Above G	cound Steel Tanks or Haul-off Rins Only (19 15 17 13 D NMAC)			
Instructions Please identify the facility or facilities for the disposal of liqui	ds, drilling fluids and drill cuttings Use attachment if more than two)		
facilities are required Disposal Facility Name:	Disposal Facility Parmit #			
Disposal Facility Name:	Disposal Facility Permit #:			
Will any of the proposed closed-loop system operations and associa				
Yes (If yes, please provide the information No Required for impacted areas which will not be used for future service and of Soil Backfill and Cover Design Specification - based upon the Re-vegetation Plan - based upon the appropriate requirements Site Reclamation Plan - based upon the appropriate requirements	he appropriate requirements of Subsection H of 19.15.17.13 N of Subsection I of 19.15 17 13 NMAC	NMAC		
17 Siting Criteria (Regarding on-site closure methods only: 19.15 17. Instructions Each siting criteria requires a demonstration of compliance in the closs certain siting criteria may require administrative approval from the appropriate distriction of consideration of approval Justifications and/or demonstrations of equivalent	ure plan Recommendauons of acceptable source material are provided below rict office or may be considered an exception which must be submitted to the S			
Ground water is less than 50 feet below the bottom of the buried water. - NM Office of the State Engineer - iWATERS database search; USG		Yes No		
Ground water is between 50 and 100 feet below the bottom of the b	puried waste	☐ ☐Yes ☐No		
- NM Office of the State Engineer - iWATERS database search; USGS		N/A		
Ground water is more than 100 feet below the bottom of the buried	waste.	☐Yes ☐No		
- NM Office of the State Engineer - iWATERS database search, USGS		∏ _{N/A}		
Within 300 feet of a continuously flowing watercourse, or 200 feet of any c (measured from the ordinary high-water mark).	other significant watercourse or lakebed, sinkhole, or playa lake	Yes No		
- Topographic map; Visual inspection (certification) of the proposed si	ite			
Within 300 feet from a permanent residence, school, hospital, institution, o - Visual inspection (certification) of the proposed site, Aerial photo, sat	••	Yes No		
Within 500 horizontal feet of a private, domestic fresh water well or spring to purposes, or within 1000 horizontal fee of any other fresh water well or spring - NM Office of the State Engineer - iWATERS database; Visual inspec	ring, in existence at the time of the initial application	Yes No		
Within incorporated municipal boundaries or within a defined municipal free pursuant to NMSA 1978, Section 3-27-3, as amended	·	Yes No		
 Written confirmation or verification from the municipality; Written a Within 500 feet of a wetland US Fish and Wildlife Wetland Identification map, Topographic map; 		Yes No		
Within the area overlying a subsurface mine.		Yes No		
- Written confiramtion or verification or map from the NM EMNRD-M Within an unstable area. - Engineering measures incorporated into the design, NM Bureau of General Conference of the Conference of the Conference of Conference of the Conference of Confe	•	Yes No		
Topographic map Within a 100-year floodplain FEMA map		Yes No		
On-Site Closure Plan Checklist: (19.15.17 13 NMAC) Instruction by a check mark in the box, that the documents are attached.	ons: Each of the following items must bee attached to the cl	osure plan. Please indicate,		
Siting Criteria Compliance Demonstrations - based upon the				
Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC				
	ased upon the appropriate requirements of 19.15.17.11 NMAG			
	rial of a drying pad) - based upon the appropriate requirement irements of 19 15 17 13 NMAC	IS 01 19.15.17.11 NMAC		
Protocols and Procedures - based upon the appropriate requ		MAC		
	e appropriate requirements of Subsection F of 19.15.17.13 NM	VIAC		
Waste Material Sampling Plan - based upon the appropriate		eds cannot be achieved)		
Soil Cover Design - based upon the appropriate requiremen		as cannot be achieved)		
Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15.17 13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19 15 17 13 NMAC				

Form C-144 Oil Conservation Division Page 4 of 5

19 Operator Application Certification:
I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief.
Name (Print): Title:
Signature: Date:
e-mail address Telephone:
OCD Approval: Permit Application (including closure plan) Closure Plan (only) OCD Conditions (see attachment) OCD Representative Signature: Approval Date: OCD Permit Number:
Closure Report (required within 60 days of closure completion): Subsection K of 1915 1713 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting the closure report. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not complete this section of the form until an approved closure plan has been obtained and the closure activities have been completed. X Closure Completion Date: May 12, 2011
Closure Method: Waste Excavation and Removal Mon-site Closure Method Alternative Closure Method Waste Removal (Closed-loop systems only) If different from approved plan, please explain
23
Closure Report Regarding Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: Instructions: Please identify the facility or facilities for where the liquids, drilling fluids and drill cuttings were disposed. Use attachment if more than two facilities
were utilized.
Disposal Facility Name Disposal Facility Permit Number
Disposal Facility Name Disposal Facility Permit Number:
Were the closed-loop system operations and associated activities performed on or in areas that will not be used for future service and operations? Yes (If yes, please demonstrate compliane to the items below)
Required for impacted areas which will not be used for future service and operations:
Site Reclamation (Photo Documentation)
Soil Backfilling and Cover Installation
Re-vegetation Application Rates and Seeding Technique
Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. X Proof of Closure Notice (surface owner and division) X Proof of Deed Notice (required for on-site closure) X Plot Plan (for on-site closures and temporary pits) X Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (if applicable) X Disposal Facility Name and Permit Number X Soil Backfilling and Cover Installation X Re-vegetation Application Rates and Seeding Technique X Site Reclamation (Photo Documentation) On-site Closure Location: Latitude: 36.99659 N Longitude: 107.65651 W NAD 1927 X 1983
25
Operator Closure Certification: I hereby certify that the information and attachments submitted with this closure report is ture, accurate and complete to the best of my knowledge and belief. I also certify that the closure complies with all applicable closure requirements and conditions specified in the approved closure plan
Name (Print): Jamie Goodwin , Title: Regulatory Tech.
Signature: Date: U/7/1/
e-mail address: / jamie.l.goodwin@conocophillips.com Telephone. 505-326-9784

Burlington Resources Oil Gas Company, LP San Juan Basin Closure Report

Lease Name: REESE MESA 7H

API No.: 30-045-35135

In accordance with Rule 19.15.17.13 NMAC the following information describes the closure of the temporary pit referenced above. All proper documentation regarding closure activities is being included with the C-144. The temporary pit for this location was constructed and location drilled before June 16, 2008 (effective date for Rule 19.15.17). While closure of the temporary pit did fall within the rule some dates for submittals are after the rig release date.

- Details on Capping and Covering, where applicable. (See report)
- Plot Plan (Pit Diagram) (Included as an attachment)
- Inspection Reports (Included as an attachment)
- Sampling Results (Included as an attachment)
- C-105 (included as an attachment)
- Copy of Deed Notice will be filed with County Clerk (Not required on Federal, State, or Tribal land as stated by FAQ dated October 30, 2008)

General Plan:

1. All free standing liquids will be removed at the start of the pit closure process from the pit and disposed of in a division—approved facility or recycle, reuse or reclaim the liquids in a manner that the appropriate division district office approves.

All recovered liquids were disposed of at Basin Disposal (Permit #NM-01-005) and any sludge or soil required to be removed to facilitate closure was hauled to Envirotech Land Farm (Permit #NM-01-011) and JFJ Landfarm % IEI (Permit #NM-01-0010B).

2. The preferred method of closure for all temporary pits will be on-site burial, assuming that all the criteria listed in sub-section (B) of 19.15.17.13 are met.

The pit was closed using onsite burial.

3. The surface owner shall be notified of BR's closing of the temporary pit as per the approved closure plan using certified mail, return receipt requested.

The closure process notification to the landowner was sent via email. (See Attached)(Well located on Federal Land, certified mail is not required for Federal Land per BLM/OCD MOU.)

4. Within 6 months of the Rig Off status occurring BR will ensure that temporary pits are closed, re-contoured, and reseeded.

Provision 4 of the closure plan requirements were not met due to rig move off date as noted on C-105 which was prior to pit rule change. Burlington will ensure compliance with this rule in the future.

- 5. Notice of Closure will be given to the Aztec Division office between 72 hours and one week of closure via email, or verbally. The notification of closure will include the following:
 - i. Operator's name
 - ii. Location by Unit Letter, Section, Township, and Range. Well name and API number.

Notification is attached.

6. Liner of temporary pit shall be removed above "mud level" after stabilization. Removal of liner will consist of manually or mechanically cutting liner at mud level and removing all remaining liner. Care will be taken to remove "All" of the liner i.e., edges of liner entrenched or buried. All excessive liner will be disposed of at a licensed disposal facility.

Liner of temporary pit was removed above "mud level" after stabilization. Removal of the liner consisted of manually cutting liner at mud level and removing all remaining liner. Care was taken to remove "ALL" of the liner i.e., edges of liner entrenched or buried. All excessive liner was disposed of at a licensed disposal facility, (San Juan County Landfill).

7. Pit contents shall be mixed with non-waste containing, earthen material in order to achieve the solidification process. The solidification process will be accomplished using a combination of natural drying and mechanically mixing. Pit contents will be mixed with non-waste, earthen material to a consistency that is deemed a safe and stable. The mixing ratio shall not exceed 3 parts clean soil to 1 part pit contents.

Burlington mixed the Pit contents with non-waste containing, earthen material in order to achieve the solidification process. The solidification process was accomplished by using a combination of natural drying and mechanically mixing. Pit contents were mixed with non-waste, earthen material to a consistency that is deemed as safe and stable. The mixing ratio consisted of approximately 3 parts clean soil to 1 part pit contents.

8. A five point composite sample will be taken of the pit using sampling tools and all samples tested per Subsection B of 19.15.17.13(B)(1)(b). In the event that the criteria are not met, all contents will be handled per Subparagraph (a) of Paragraph (1) of Subsection B of 19.15.17.13 i.e., Dig and haul.

A five point composite sample was taken of the pit using sampling tools and all samples tested per Subsection B of 19.15.17.1 3(B)(1)(b). (Sample results attached).

Components	Tests Method	Limit (mg/Kg)	Results
Benzene	EPA SW-846 8021B or 8260B	0.2	6.2 ug/kg
BTEX	EPA SW-846 8021B or 8260B	50	134 ug/kG
TPH	EPA SW-846 418.1	2500	142mg/kg
GRO/DRO	EPA SW-846 8015M	500	ND mg/Kg
Chlorides	EPA 300.1	1000/500	270 mg/L

9. Upon completion of solidification and testing standards being passed, the pit area will be backfilled with compacted, non-waste containing, earthen material. A minimum of four feet of cover shall be achieved and the cover shall include one foot of suitable material to establish vegetation at the site, or the background thickness of topsoil, whichever is greater. If standard testing fails BR will dig and haul all contents pursuant to 19.15.17.13.i.a. After doing such, confirmation sampling will be conducted to ensure a release has not occurred.

The pit material passed solidification and testing standards. The pit area was then backfilled with compacted, non-waste containing, earthen material. More than four feet of cover was achieved and the cover included one foot of suitable material to establish vegetation at the site.

10. During the stabilization process if the liner is ripped by equipment the Aztec OCD office will be notified within 48 hours and the liner will be repaired if possible. If the liner can not be repaired then all contents will be excavated and removed.

The integrity of the liner was not damaged in the pit closure process.

11. Dig and Haul Material will be transported to the Envirotech Land Farm located 16 miles south of Bloomfield on Angel Peak Road, CR 7175. Permit # NM010011

Dig and Haul was not required.

12. Re-contouring of location will match fit, shape, line, form and texture of the surrounding. Re-shaping will include drainage control, prevent ponding, and prevent erosion. Natural drainages will be unimpeded and water bars and/or silt traps will be place in areas where needed to prevent erosion on a large scale. Final recontour shall have a uniform appearance with smooth surface, fitting the natural landscape.

The pit area was re-contoured to match fit, shape, line, form and texture of the surrounding area. Reshaping included drainage control, to prevent ponding and erosion. Natural drainages were unimpeded and water bars and/or silt traps were placed in areas where needed to prevent erosion on a large scale. Final recontour has a uniform appearance with smooth surface, fitting the natural landscape.

13. Notification will be sent to OCD when the reclaimed area is seeded.

Provision 13 was accomplished through complying with BLM seeding requirements as allowed by the BLM/OCD MOU.

14. BR shall seed the disturbed areas the first growing season after the operator closes the pit. Seeding will be accomplished via drilling on the contour whenever practical or by other division-approved methods. BLM or Forest Service stipulated seed mixes will used on federal lands. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintain that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs.

Provision 14 was accomplished through complying with BLM seeding requirements as allowed by the BLM/OCD MOU.

15. The temporary pit will be located with a steel marker, no less than four inches in diameter, cemented in a hole three feet deep in the center of the onsite burial upon the abandonment of all the wells on the pad. The marker will be flush with the ground to allow access of the active well pad and for safety concerns. The marker will include a threaded collar to be used for future abandonment. The top of the marker will contain a welded steel 12" square plate that indicates the onsite burial of the temporary pit. The plate will be easily removable and a four foot tall riser will be threaded into the top of the collar marker and welded around the base with the operator's information at the time of all wells on the pad are abandoned. The operator's information will include the following: Operator Name, Lease Name, Well Name and number, Unit Number, Section, Township, Range and an indicator that the marker is an onsite burial location.

Provision 15 was accomplished by installing a steel marker in the temporary pit, no less than four inches in diameter, cemented in a hole three feet deep in the center of the onsite burial. The marker is flush with the ground to allow access of the active well pad and for safety concerns. The top of the marker contains a welded steel 12" square plate that indicates the onsite burial of the temporary pit. The plate contains the following: Operator Name, Lease Name, Well Name and number, Unit Number, Section, Township, Range and an indicator that the marker is an onsite burial location.

The plate will be easily removable and a four foot tall riser will be threaded into the top of the collar marker and welded around the base with the following operator's information at the time of all wells on the pad are abandoned. The riser will be labeled: BR, BLM, REESE MESA 7H, UL-I, Sec. 10, T 32N, R 8W, API # 30-045-35135

Jaramillo, Marie E

From:

Jaramillo, Marie E

Sent:

Thursday, April 01, 2010 12:31 PM

To:

Subject:

'mark_kelly@nm.blm.gov' SURFACE OWNER NOTIFICATION 03/31/10

The subject well will have a temporary pit that will be closed on site. Please let me know if you have any questions. Thanks

REESE MESA 75

Marie Jaramillo Staff Regulatory Tech. ConocoPhillips Office # (505) 326-9865 Fax # (505) 599-4062 mailto:marie.e.jaramillo@conocophillips.com DISTRICT I 1625 N. French Dr., Hobbs, N.M. 68240

State of New Mexico Energy, Minerals & Natural Resources Department

Form C-102 Revised October 12, 2005

DISTRICT II 1301 W. Grand Avenue, Artesia, N.M. 88210

1000 Rio Brazos Rd., Aztec, N.M. 87410

1

OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies

☐ AMENDED REPORT

DISTRICT IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

WELL LOCATION AND ACREAGE DEDICATION PLAT


^t API Number	Pool Code			¹ API Number				"Pool Name BASIN FRUITLAND COAL			
⁴ Property Code				Property REESE			•	Well Number 7 S			
OGRID No.		*Operator Name BURLINGTON RESOURCES OIL & GAS COMPANY LP				* Elevation 7002*					
				10 Surface	Location						
UL or lot no. Sectio	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County			

Section Township Range Lot Idn Feet from the North/South line Feet from the East/West line County 1305' SAN JUAN 10 32N 8W 1215' **NORTH EAST** 11

> 11 Bottom Hole Location If Different From Surface

UL or lot no.	Section 11	Township 32N	Range 8W	Lot Idn 10	Feet from the 710'	North/South line NORTH	Feet from the 1887'	East/West line WEST	County SAN JUAN
Dedicated Acre	8		¹³ Joint or	nfill	16 Consolidation C	ode	15 Order No.		
293.65 A	\cres						R-905	5	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED



WELL FLAG

LATITUDE: 36.99659°N LONGITUDE: 107.65681°W

CENTER OF PIT


LATITUDE: 36.99659° N LONGITUDE: 107.65651° W ELEVATION: 6989.9' DATUM: NAD83 & NAVD88


BURLINGTON RESOURCES OIL & GAS COMPANY LP

REESE MESA #7 S 1215' FNL & 1305' FEL LOCATED IN THE NW/4 SE/4 OF SECTION 10, T32N, R8W, N.M.P.M.,

SAN JUAN COUNTY, NEW MEXICO **GROUND ELEVATION: 7002', NAVD 88**

FINISHED PAD ELEVATION: 7001.9', NAVD 88





SLOPES TO BE CONSTRUCTED TO MATCH THE ORIGINAL CONTOURS AS CLOSE AS POSSIBLE.

JOB No.: COPC137 REV6

DATE: 02/15/10

NOTE: 330' x 400' = 3.03 ACRES OF DISTURBANCE RESERVE PIT DIKE: TO BE 8' ABOVE DEEP SIDE (OVERFLOW - 3' WIDE AND 1' ABOVE SHALLOW SIDE). SCALE: 1" = 60' RUSSELL SURVEYING, INC. IS NOT LIABLE FOR UNDERGROUND UTILITIES OR PIPELINES. CONTRACTOR SHOULD CALL ONE-CALL FOR LOCATION OF ANY MARKED OR UNMARKED, BURIED PIPELINES OR CABLES ON WELL PAD. IN CONSTRUCTION ZONE AND/OR ACCESS ROAD AT LEAST TWO (2) WORKING DAYS PRIOR TO CONSTRUCTION.



Russell Surveying 1409 W. Aztec Blvd. #2 Aztec. New Mexico 87410 (505) 334-8637



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Back Ground	Date Reported:	11-02-10
Laboratory Number:	56345	Date Sampled:	11-01-10
Chain of Custody No:	10593	Date Received:	11-01-10
Sample Matrix:	Soil	Date Extracted:	11-01-10
Preservative:	Cool	Date Analyzed:	11-02-10
Condition:	Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum Hydrocarbons	ND	

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

Reese Mesa #7H

Analyst



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Reserve Pit	Date Reported:	11-02-10
Laboratory Number:	56346	Date Sampled:	11-01-10
Chain of Custody No:	10593	Date Received:	11-01-10
Sample Matrix:	Soil	Date Extracted:	11-01-10
Preservative:	Cool	Date Analyzed:	11-02-10
Condition:	Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum Hydrocarbons	ΝD	

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

Reese Mesa #7H

Analyst



EPA Method 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Quality Assurance Report

Client:	QA/QC	Project #:	N/A
Sample ID:	11-02-10 QA/QC	Date Reported:	11-02-10
Laboratory Number:	56343	Date Sampled:	N/A
Sample Matrix:	Methylene Chloride	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	11-02-10
Condition:	N/A	Analysis Requested:	TPH

	(ECall Dáite	l⊧CaliRF	C-Callin	% Difference	- Accept Range
Gasoline Range C5 - C10	11-02-10	9.9960E+002		0.04%	0 - 15%
Diesel Range C10 - C28	11-02-10	9.9960E+002	1.0000E+003	0.04%	0 - 15%

Blank Conc. (mg/L-mg/Kg)	Concentration	Detection Limit
Gasoline Range C5 - C10	ND	0.2
Diesel Range C10 - C28	ND	0.1

Dublicate Cone. (mg/Kg)	Sample	Duplicate	% Difference	Accept Renge
Gasoline Range C5 - C10	ND	ND	0.0%	0 - 30%
Diesel Range C10 - C28	93.3	95.8	2.7%	0 - 30%

Spike Gong (mg/Kg)	Sample	Spike/Added	Spike Result	% Recovery	Accepte Range
Gasoline Range C5 - C10	ND	250	252	101%	75 - 125%
Diesel Range C10 - C28	93.3	250	359	105%	75 - 125%

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

QA/QC for Samples 56343, 56345-56348

Analyst



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Back Ground	Date Reported:	11-02-10
Laboratory Number:	56345	Date Sampled:	11-01-10
Chain of Custody:	10593	Date Received:	11-01-10
Sample Matrix:	Soil	Date Analyzed:	11-02-10
Preservative:	Cool	Date Extracted:	11-01-10
Condition:	Intact	Analysis Requested:	BTEX
		Dilution:	10

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)	
Benzene	ND	0.9	
Toluene	ND	1.0	
Ethylbenzene	ND	1.0	
p,m-Xylene	ND	1.2	
o-Xylene	ND	0.9	
Total BTEX	ND		

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	101 %
	1,4-difluorobenzene	99.1 %
	Bromochlorobenzene	101 %

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

Reese Mesa #7H

Analyst



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Reserve Pit	Date Reported:	11-02-10
Laboratory Number:	56346	Date Sampled:	11-01-10
Chain of Custody:	10593	Date Received:	11-01-10
Sample Matrix:	Soil	Date Analyzed:	11-02-10
Preservative:	Cool	Date Extracted:	11-01-10
Condition:	Intact	Analysis Requested:	BTEX
		Dilution:	10

		Det.	
	Concentration	Limit	
Parameter	(ug/Kg)	(ug/Kg)	
Benzene	6.2	0.9	
Toluene	41.2	1.0	
Ethylbenzene	5.6	1.0	
p,m-Xylene	60.1	1.2	
o-Xylene	20.5	0.9	
Total BTEX	134		

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	96.7 %
	1,4-difluorobenzene	98.2 %
	Bromochlorobenzene	96.8 %

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

Reese Mesa #7H

Añalyst



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	N/A		Project #:		N/A	
Sample ID:	1102BBLK QA/Q0	3	Date Reported:		11-02-10	
Laboratory Number:	56343		Date Sampled:		N/A	
Sample Matrix:	Soil		Date Received:		N/A	
Preservative:	N/A		Date Analyzed:		11-02-10	
Condition:	N/A		Analysis:		BTEX	
			Dilution:		10	
Calibration and	#OaliRF	C-CallRF:	%Diff	Blank	Detect	
Calibration and		C-CallRF:	%Diff:	Blank Conc	Detect	
Calibration and Detection Limits (ug/L)		©-CallRF Accept Rang		Blank Conc		
Detection Limits (ug/L)		Accept Rang	je:0:-15%	Conc,	Limit	
Detection Limits (ug/L) Benzene	4.7806E+005	Accept Rand	ge 0 = 15%	Conc.	Limit 0,1	
Detection Limits (ug/L) Benzene Toluene	4.7806E+005 5.5715E+005	Accept Rand 4.7902E+005 5.5827E+005	0.2% 0.2% 0.2%	Conc. ND ND	Limit*** 0.1 0.1	

Duplicate Conc. (ug/Kg).	Sample Du	plicate	%Diff	Accept Range	Detect: Limit
Benzene	ND	ND	0.0%	0 - 30%	0.9
Toluene	ND	, ND	0.0%	0 - 30%	1.0
Ethylbenzene	ND	ND	0.0%	0 - 30%	1.0
p,m-Xylene	ND	ND	0.0%	0 - 30%	1.2
o-Xylene	ND	ND	0.0%	0 - 30%	0.9

Spike(Conc.:(ug/Kg).	Sample Amo	untSpiked Spi	ked/Sample %	Recovery	AcceptiRange	See
Benzene	ND	500	498	100%	39 - 150	
Toluene	ND	500	497	99.3%	46 - 148	
Ethylbenzene	ND	500	507	101%	32 - 160	
p,m-Xylene	ND	1000	1,010	101%	46 - 148	
o-Xylene	ND	500	503	101%	46 - 148	

ND - Parameter not detected at the stated detection limit.

Dilution: Spike and spiked sample concentration represent a dilution proportional to sample dilution.

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic and Halogenated Volatiles by Gas Chromatography Using Photoionization and/or Electrolytic Conductivity Detectors, SW-846, USEPA December 1996.

Comments:

QA/QC for Samples 56343, 56345-56348

. . . Analyst

EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Back Ground	Date Reported:	11-02-10
Laboratory Number:	56345	Date Sampled:	11-01-10
Chain of Custody No:	10593	Date Received:	11-01-10
Sample Matrix:	Soil	Date Extracted:	11-02-10
Preservative:	Cool	Date Analyzed:	11-02-10
Condition:	Intact	Analysis Needed:	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons

18.1

9.7

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

Reese Mesa #7H

Analyst

EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Reserve Pit	Date Reported:	11-02-10
Laboratory Number:	56346	Date Sampled:	11-01-10
Chain of Custody No:	10593	Date Received:	11-01-10
Sample Matrix:	Soil	Date Extracted:	11-02-10
Preservative:	Cool	Date Analyzed:	11-02-10
Condition:	Intact	Analysis Needed:	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons

142

9.7

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

Reese Mesa #7H

Analyst



EPA METHOD 418.1 TOTAL PETROLEUM HYROCARBONS QUALITY ASSURANCE REPORT

Client:	QA/QC	Project #:	N/A
Sample ID:	QA/QC	Date Reported:	11-02-10
Laboratory Number:	11-02-TPH.QA/QC 56345	Date Sampled:	N/A
Sample Matrix:	Freon-113	Date Analyzed:	11 -02- 10
Preservative:	N/A	Date Extracted:	11-02-10
.			

Condition: N/A Analysis Needed: TPH

| Calibration | Gale | Calibration | Calibra

Blank Gonc..(mg/kg) Concentration Detection Limit ND 9.7

Düplicate Conc. (mg/Kg) Sample Duplicate Molfference Accept. Range 18.1 19.4 7.2% +/- 30%

 Spike/Conc:
 (mg/Kg)
 Sample
 Spike/Added
 Spike/Result
 %/Recovery
 Accept Range

 TPH
 18.1
 2,000
 1,900
 94.1%
 80 - 120%

ND = Parameter not detected at the stated detection limit.

References: Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments: QA/QC for Samples 56345-56348

Review

Analyst



Chloride

Client: ConocoPhillips 96052-1706 Project #: **Back Ground** Sample ID: Date Reported: 11-02-10 Lab ID#: 56345 11-01-10 Date Sampled: Sample Matrix: Soil Date Received: 11-01-10 Preservative: Cool Date Analyzed: 11-02-10 Condition: Intact Chain of Custody: 10593

Parameter

Concentration (mg/Kg)

Total Chloride

20

Reference:

U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983. Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments:

Reese Mesa #7H

Analyst



Chloride

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Reserve Pit	Date Reported:	11-02-10
Lab ID#:	56346	Date Sampled:	11-01-10
Sample Matrix:	Soil	Date Received:	11-01-10
Preservative:	Cool	Date Analyzed:	11-02-10
Condition:	Intact	Chain of Custody:	10593

Parame	eter
--------	------

Concentration (mg/Kg)

Total Chloride

270

Reference:

U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983. Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments:

Reese Mesa #7H

Analyst

Submit To Appropr Two Copies	iate Distric	t Office				State of Ne			-								rm C-105
District I 1625 N. French Dr.	, Hobbs, N	M 88240		Ene	ergy, I	Minerals and	d Nat	ural F	Res	sources	ŀ	1. WELL	API N	NO.		J	uly 17, 2008
District II 1301 W. Grand Ave	enue, Artes	ıa, NM 88210	,		Oil	l Conservat	tion I	Divis	in	n		30-045-351	35			=	
District III 1000 Rio Brazos Ro	I, Aztec, N	IM 87410				20 South S						2. Type of Le		☐ FEE	I ∑1	FED/INDI	AN
District IV 1220 S. St. Francis	Dr., Santa I	Fe, NM 8750	5			Santa Fe, N	NM 8	37505	5		ŀ	3. State Oil &	& Gas			LEPRINE	7 H.V
\\/ELL(OMDI	ETION		DECC	MDI	ETION RE		Τ Λ Ν	חו	U OG		NM - 6889					
4. Reason for fili		LETION	OKI	\LCC	IVIF L	LIIONINE	FUN	. 1 /1	שו	LOG	- 1	5. Lease Nam	e or U	nit Agree	ment l	Name	
☐ COMPLETI	ON REP	ORT (Fill i	n boxes	#1 throu	gh #31	for State and Fe	e wells	only)			ļ	6. Well Numb				_	
☑ C-144 CLOS									od s	and #32 and/o	<u></u>	7H	er.				
#33; attach this a	nd the pla																
7. Type of Comp] worko	VER [DEEPE	ENING	□PLUGBACI	к 🗆 г	OIFFER	REN	T RESERVO	OIR	OTHER					
8. Name of Opera Burlington R		e Oil Ce	s Con	nany	I D		•					9. OGRID 14538					
10. Address of O	perator			ірану,							7	11. Pool name	or W	ildcat		_	
PO Box 4298, Fa	rmington,	, NM 87499															
12.Location	Unit Ltr	Sectio	n	Towns	hip	Range	Lot			Feet from th	ie	N/S Line	Feet	from the	E/V	V Line	County
Surface:							ļ		_	-	4		<u> </u>			_	
13. Date Spudded	1 14 D	ate T.D. Re	ched	 	Date Ric	Released		1	16	Date Comple	eted	(Ready to Proc	luce)		7 Flex	vations (DF	and RKR
				9/25	/2010									R	T, GR	l, etc.)	
18. Total Measur	ed Depth	of Well		19. F	Plug Bac	ck Measured De	pth	2	20.	Was Direction	ona	l Survey Made	?	21. Тур	e Elec	etric and Ot	her Logs Run
22. Producing Int	erval(s), o	of this comp	letion -	Top, Bot	tom, Na	ame								l	· · · · · · · · · · · · · · · · · · ·		
23.					CAS	ING REC	ORI) (Re	no	ort all str	inc	re set in w					
CASING SI	ZE	WEIG	HT LB./	FT.	CAS	DEPTH SET				LE SIZE	1112	CEMENTIN		CORD		AMOUNT	PULLED
										 -						_	
																	
24.	1				LIN	ER RECORD					25.	1	ממוזי	NG REC	ODD	_	
SIZE	TOP		BO	ттом	LIIV	SACKS CEM	ENT	SCRE	EN		SIZ			EPTH SE		PACKI	ER SET
							-						_				
26. Perforation	record (ii	nterval, size	, and nu	mber)		.]		27. A	CI	ID, SHOT, I	FRA	ACTURE, CE	MEN	IT. SOU	EEZE	E, ETC.	
										INTERVAL		AMOUNT A					
28.		•	ъ .							FION		1					
Date First Produc	cuon		Product	ion Met	noa (Fia	owing, gas lift, p	umping	g - Size	anc	d type pump)		Well Status	s (Pro	a. or Shut	- <i>in)</i>		
Date of Test	Hours	Tested	Ch	oke Size		Prod'n For Test Period		Oil - I	Bbl		Gas	s - MCF	w	ater - Bbl		Gas - C	oil Ratio
Flow Tubing Press.	Casin	g Pressure		culated : ur Rate	24-	Oil - Bbl.		Ğ	as -	- MCF		Water - Bbl.		Oil Gra	vity -	API - (Cori	r.)
29. Disposition o	f Gas (So	ld, used for	fuel, ven	ted, etc.,		1							30.	Test Witne	essed I	Ву	
31. List Attachm	ents												l		****		
32. If a temporary	y pit was i	used at the	vell, atta	ch a plat	with th	e location of the	tempo	rary pit	t.				-				
33. If an on-site	ourial was																
I hereby certi	fy that ti	Latity he inform	de 36.9 ation s	9659°N hown o	Longon bott	gitude 107.6565 h sides of this	51°W 5 form	NAD [<u>]</u> 1	927 ⊠1983 and comple	ete	to the best o	of mv	knowle	dge a	and belief	•
Signature	hmi	J (SIX	- 1	•	Pri	nted ne Jamie Go				_				e: 6/7/20			
E-mail Addre	ss iami	e Lønndu		•													

ConocoPhillips

Pit Closure Form:
Date: _5//2 / //
Well Name: Recse Mess >H
Footages: 1215 FNL 1305 FFL Unit Letter:
Section: 10 , T- 32 -N, R- 8 -W, County: 5 - 7 - 9 -State: 10
Contractor Closing Pit:
ý.
Construction Inspector: 5. MEGI(45507 Date: 5/12/11)
Inspector Signature:

Revised 11/4/10

Office Use Only: Subtask _____ DSM _____ Folder _____

Goodwin, Jamie L

From: Payne, Wendy F

Sent: Monday, May 02, 2011 12:31 PM

(Brandon Powell@state nm. us): Fli (Cimarron) (eliv@gwestoffice net): GRP:S II

To: (Brandon.Powell@state.nm.us); Eli (Cimarron) (eliv@qwestoffice.net); GRP:SJBU Regulatory; Mark Kelly; Robert Switzer; Sherrie Landon; Bassing, Kendal R.; Berenz

(mxberenz@yahoo.com); Elmer Perry; Faver Norman; Fred Martinez; Jared Chavez; Lowe, Terry; Payne, Wendy F; Spearman, Bobby E; Steve McGlasson; Tally, Ethel; Becker, Joey W; Bowker, Terry D; Gordon Chenault; GRP:SJBU Production Leads; Hockett, Christy R;

Johnson, Kirk L; Bassing, Kendal R.; Kennedy, Jim R; Lopez, Richard A; O'Nan, Mike J.; Peace, James T; Pierce, Richard M; Poulson, Mark E; Smith, Randall O; Spearman, Bobby E; Stamets, Steve A; Thacker, LARRY; Work, Jim A; Corey Alfandre; 'isaiah@crossfire-llc.com'; Jerid Cabot (jerid@crossfire-llc.com); Blair, Maxwell O; Blakley, Mac; Farrell, Juanita R; Gillette, Steven L (PAC); Hines, Derek J; Maxwell, Mary Alice; McWilliams, Peggy L; Seabolt,

Elmo F; Stallsmith, Mark R; Thayer, Ashley A

Cc: 'acedragline@yahoo.com'

Subject: Reclamation Notice: Reese Mesa 7H

Importance: High

Attachments: REESE MESA 7H was 7S.pdf

Ace Services will move a tractor to the Reese Mesa 7H to start the reclamation process on Wednesday, May 4, 2011. Please contact Steve McGlasson (716-3285) if you have questions or need further assistance.



REESE MESA 7H was 7S.pdf (19 K...

Burlington Resources Well - Network # 10285026 - Activity Code D250 (reclamation) & D260 (pit closure) - PO: Kaitlw San Juan County, NM

Reese Mesa 7H - BLM-surface/BLM-mineral

Onsite: Roger Herrera - 11-13-08

Twin: n/a

1215' FNL, 1305' FEL Sec.10, T32N, R8W Unit Letter ' I ' Lease # NM-6890

BH: NESW, Sec.11,T32N, R8W Latitude: 36° 59' 48" N (NAD 83) Longitude: 107° 39' 25" W (NAD 83)

Elevation: 7002'

Total Acres Disturbed: 1.86 acres

Access Road: 300 feet API # 30-045-35135 Within City Limits: NO

Pit Lined: YES

Note: Arch Monitoring is Required - SWCA - 970-385-8566

Wendy Payne ConocoPhillips-SJBU 505-326-9533

Wendy.F.Payne@conocophillips.com

ConocoPhillips

Reclamation Form:
Date: 6/1 / 11
Well Name: Rose Mosa 7H
Footages: 1215 FNL 1305 FEL Unit Letter:
Section:, T- <u>32</u> -N, R- <u>8</u> -W, County: <u>Sau Juan</u> State:
Reclamation Contractor:
Reclamation Date: 5/16/11
Road Completion Date: 5/18/1/
Seeding Date: 5/19/11
**PIT MARKER STATUS (When Required): Picture of Marker set needed
MARKER PLACED: 5/19/// (DATE)
MARKER PLACED: 5/19/// (DATE)
MARKER PLACED: 5/19/// (DATE) LATATUDE: 36° 59.784' LONGITUDE: 107° 39.399'
MARKER PLACED: 5/19/// (DATE) LATATUDE: 36° 59.784' LONGITUDE: 107° 39.399'
MARKER PLACED: 5/19/// (DATE) LATATUDE: 36° 59.784' LONGITUDE: 107° 39.399' Pit Manifold removed 5/2/// (DATE)
MARKER PLACED: $\frac{5/49/1/}{126}$ (DATE) LATATUDE: $\frac{36^{\circ}}{36^{\circ}}$ $\frac{59.784^{\circ}}{39.399^{\circ}}$ Pit Manifold removed $\frac{5/2/1/}{26}$ (DATE) Construction Inspector: $\frac{5}{26^{\circ}}$ Date: $\frac{6/1/1/}{26^{\circ}}$

BURLINGTON BESOURCES

REESE MESA #7H

LATITUDE 36° 59 MIN. 48 SEC. N (NAD 83)

LONGITUDE 107° 39 MIN. 25 SEC. W (NAD 83)

UNIT I SEC 10 T32N RO8W


BH: NESW SEC 111 T32N RO8W


1215' FNL 1305' FEL API# 30-045-35135

LEASE# NM-6890 ELEV. 7002'

SAN JUAN COUNTY, NEW MEXICO







	WELL NAME:	OPEN PIT INSPECTION FORM					ConocoPhillips			
	Reese Mesa#7H					The state of the s				
	INSPECTOR		Fred Mtz	Fred Mtz	Fred Mtz	Fred Mtz	Fred Mtz	Fred Mtz	Fred Mtz	Fred Mtz
<u> </u>	DATE		01/10/11	01/17/11	02/07/11	02/15/11	02/23/11	03/01/11	03/08/11	03/16/11
*Please request for pit extention after 26 weeks		Week 1	Week 2	Week 3	Week 4	Week 5	Week 6	Week 7	Week 8	Week 9 ✓ Drilled
	DI 07 1 7 1 0	✓ Dnlled ✓ Completed	✓ Drilled ✓ Completed	✓ Drilled ✓ Completed	☐ Drilled☐ Completed	✓ Drilled ☐ Completed	✓ Drilled ✓ Completed	✓ Drilled ✓ Completed	✓ Drilled ✓ Completed	✓ Drilled ✓ Completed
	PIT STATUS		Clean-Up	Clean-Up	☐ Completed	Clean-Up	Clean-Up	Clean-Up	Clean-Up	Clean-Up
<u> </u>		☐ Clean-Up	☐ Clean-Up	☐ Clean-up	☐ Clean-Up	L Clean-Up	☐ Clean-Up	☐ Clean-Up	☐ Clean-Up	Cleari-up
LOCATION	Is the location marked with the proper flagging? (Const. Zone, poles, pipelines, etc.)	☑ Yes ☐ No	✓ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No	☑ Yes ☐ No	✓ Yes ☐ No	✓ Yes ☐ No
10C/	Is the temporary well sign on location and visible from access road?	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes No	☑ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No
	Is the access road in good driving condition? (deep ruts, bladed)	☐ Yes ☑ No	Yes No	☐ Yes ☑ No	✓ Yes ☐ No	☑ Yes ☐ No	✓ Yes □ No	✓ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No
	Are the culverts free from debris or any object preventing flow?	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No	☑ Yes ☐ No	· ✓ Yes No	✓ Yes □ No	☑ Yes ☐ No	✓ Yes 🗌 No
	Is the top of the location bladed and in good operating condition?	☐ Yes ☑ No	☑ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No
IAN	Is the fence stock-proof? (fences tight, barbed wire, fence clips in place?	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No	✓ Yes □ No	✓ Yes □ No	✓ Yes 🗌 No	☑ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No
COMPLIANCE	Is the pit liner in good operating condition? (no tears, up-rooting corners, etc.)	☑ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes □ No	✓ Yes □ No	✓ Yes 🗌 No	✓ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No
_	Is the the location free from trash, oil stains and other materials? (cables, pipe threads, etc.)	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No	✓ Yes □ No	☑ Yes ☐ No	✓ Yes □ No	✓ Yes □ No	☑ Yes ☐ No
NWE	Does the pit contain two feet of free board? (check the water levels)	☑ Yes ☐ No	✓ Yes □ No	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes □ No	☑ Yes ☐ No	✓ Yes □ No	✓ Yes □ No	✓ Yes ☐ No
ENVIRONMENTAL	Is there any standing water on the blow pit?	✓ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes ☐ No
"	Are the pits free of trash and oil?	✓ Yes ☐ No	✓ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No
Ì	Are there diversion ditches around the pits for natural drainage?	☑ Yes ☐ No	✓ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No	✓ Yes No	☑ Yes ☐ No
	Is the Manifold free of leaks? Are the hoses in good condition?	☑ Yes ☐ No	✓ Yes ☐ No	✓ Yes □ No	✓ Yes □ No	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes □ No	✓ Yes 🗌 No	✓ Yes 🗌 No
၁၀	Was the OCD contacted?	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No
	PICTURE TAKEN	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	Yes 🗸 No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	Yes 🗸 No	☐ Yes ☑ No
	COMMENTS	Road and location are snowy.		Road and location needs bladed road has tear drop.	Location needs bladed.	Location needs bladed.	Location needs bladed.	Location needs bladed.	Location needs bladed	Location needs bladed.

WELL NAME: Reese Mesa#7H										
	INSPECTOR	Fred Mtz	Fred Mtz	Fred Mtz	Fred Mtz	Fred Mtz	Fred Mtz	Fred Mtz	Fred Mtz	Fred Mtz
	DATE	03/24/11	03/30/11					04/08/11	04/15/11	04/29/11
	*Please request for pit extention after 26 weeks	Week 10	Week 11	Week 12	Week 13	Week 14	Week 15	Week 16	Week 17	Week 18
1		✓ Drilled	☑ Drilled	☐ Drilled	☐ Drilled	☐ Drilled	☐ Drilled	☑ Drilled	✓ Drilled	☑ Dnilled
1	PIT STATUS	✓ Completed	✓ Completed	Completed	Completed	Completed	Completed	✓ Completed	Completed	✓ Completed
		☐ Clean-Up	☐ Clean-Up	Clean-Up	Clean-Up	☐ Clean-Up	Clean-Up	☐ Clean-Up	☐ Clean-Up	☐ Clean-Up
CATION	Is the location marked with the proper flagging? (Const. Zone, poles, pipelines, etc.)	☑ Yes ☐ No	✓ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	✓ Yes ☐ No	✓ Yes ☐ No	✓ Yes ☐ No
700	Is the temporary well sign on location and visible from access road?	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☑ No	✓ Yes 🗌 No
	Is the access road in good driving condition? (deep ruts, bladed)	☑ Yes ☐ No	✓ Yes □ No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	Yes No	✓ Yes 🗌 No	☑ Yes ☐ No	☑ Yes ☐ No
	Are the culverts free from debris or any object preventing flow?	✓ Yes ☐ No	✓ Yes 🗌 No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☑ Yes ☐ No	☐ Yes ☑ No	✓ Yes □ No
"	is the top of the location bladed and in good operating condition?	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes ☐ No
OMPLIANC	is the fence stock-proof? (fences tight, barbed wire, fence clips in place?	☑ Yes ☐ No	☑ Yes ☐ No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No
SO MP	Is the pit liner in good operating condition? (no tears, up-rooting corners, etc.)	✓ Yes 🗌 No	☑ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No
MAL	Is the the location free from trash, oil stains and other materials? (cables, pipe threads, etc.)	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	✓ Yes □ No	☐ Yes ☑ No	✓ Yes 🗌 No
ENVIRONMENTAL	Does the pit contain two feet of free board? (check the water levels)	✓ Yes 🗌 No	☑ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No
N N N N	Is there any standing water on the blow pit?	☑ Yes ☐ No	☑ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No	☑ Yes ☐ No
"	Are the pits free of trash and oil?	✓ Yes ☐ No	☑ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No	✓ Yes 🗌 No
	Are there diversion ditches around the pits for natural drainage?	✓ Yes ☐ No	✓ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	☑ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No
	Is the Manifold free of leaks? Are the hoses in good condition?	☑ Yes ☐ No	☑ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☑ Yes ☐ No	☑ Yes 🗌 No	✓ Yes 🗌 No
ပ္ပ	Was the OCD contacted?	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No
	PICTURE TAKEN	Yes 🗹 No	☐ Yes ☑ No	☐ Yes ☑ No	Yes No	Yes No	Yes No	☐ Yes ☑ No	☐ Yes ☑ No	Yes 🗹 No
		Has oil around well head from stuffing box leaking: sign on fence; location needs bladed	Has oil around well head from stuffing box leaking; sign on fence, location needs bladed		·			No repairs w. head is leg king grand stuffing bot.	Location needs bladed location sign on fence all around with head.	Contact M -N-R to pull pit

	WELL NAME:	and all requi								
Reese Mesa#7H								, m , y , y , y , y , y , y , y , y , y		
	INSPECTOR									
\vdash	*Please request for pit extention after 26 weeks	05/05/11 Week 19	Week 20	Week 21	Week 22	Week 23	Week 24	Week 25	*Week 26*	Week 27
PIT STATUS		☑ Drilled ☑ Completed ☐ Clean-Up	☐ Dnilled☐ Completed☐ Clean-Up	☐ Drilled☐ Completed☐ Clean-Up	Drilled Completed Clean-Up	☐ Drilled☐ Completed☐ Clean-Up	☐ Drilled ☐ Completed ☐ Clean-Up	Drilled Completed Clean-Up	☐ Drilled☐ Completed☐ Clean-Up	☐ Drilled ☐ Completed ☐ Clean-Up
LOCATION	Is the location marked with the proper flagging? (Const. Zone, poles, pipelines, etc.)	☑ Yes ☐ No	Yes No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
	Is the temporary well sign on location and visible from access road?	☑ Yes ☐ No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	Yes No	Yes No
	Is the access road in good driving condition? (deep ruts, bladed)	✓ Yes □ No	Yes No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	Yes No	Yes No	Yes No
	Are the culverts free from debris or any object preventing flow?	☑ Yes ☐ No	☐ Yes ☐ No	Yes No	Yes No	Yes No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No
<u> </u>	Is the top of the location bladed and in good operating condition?	✓ Yes 🗌 No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
COMPLIANCE	Is the fence stock-proof? (fences tight, barbed wire, fence clips in place?	☑ Yes ☐ No	Yes No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
S S	Is the pit liner in good operating condition? (no tears, up-rooting corners, etc.)	✓ Yes □ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No
	Is the the location free from trash, oil stains and other materials? (cables, pipe threads, etc.)	✓ Yes □ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No
ENVIRONMENTAL	Does the pit contain two feet of free board? (check the water levels)	☑ Yes ☐ No	☐ Yes ☐ No	☑ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
 	Is there any standing water on the blow pit?	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No
	Are the pits free of trash and oil?	☑ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No
	Are there diversion ditches around the pits for natural drainage?	☑ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
	Is the Manifold free of leaks? Are the hoses in good condition?	✓ Yes 🗌 No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No
ပ္ပ	Was the OCD contacted?	☐ Yes ☑ No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	Yes No	☐ Yes ☐ No
	PICTURE TAKEN	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	Yes No	Yes No	Yes No
	COMMENTS									