State of New Mexico 1625 N French Dr , Hobbs, NM 88240 . Energy Minerals and Natural Resources Department 1301 W. Grand Avenue, Artesia, NM-88210 | V = Oil Conservation Division 1220 South St. Francis Dr. | 11 41 Santa Fe, NM 87505 District III
1000 Rio Brazos Road, Aztec, NM 87410— District IV 1220 S. St. Francis Dr., Santa F2019 120 16

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office.
For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Pit, Closed-Loop System, Below-Grade Tank, or Proposed Alternative Method Permit or Closure Plan Application

Type of action:	Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method
Existing BGT	Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method
	Modification to an existing permit
	Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system,
below-grade tanl	s, or proposed alternative method

Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request

Please be advised that approval of this request does not relieve the operator of liability environment. Nor does approval relieve the operator of its responsibility to comply w	
1,	
Operator: XTO Energy, Inc.	
Address: #382 County Road 3100, Aztec, NM 87410	•
Facility or well name: Hargrave RP M#1	
API Number: 30-045-30148 OCD	
U/L or Qtr/Qtr <u>C</u> Section <u>09</u> Township <u>27N</u> I	Range 10W County: San Juan
Center of Proposed Design: Latitude 36.59489 Lon	gitude <u>107.9027</u> NAD: □1927 🛛 1983
Surface Owner: ☑ Federal ☐ State ☐ Private ☐ Tribal Trust or Indian Allot	ment
2	
Pit: Subsection F or G of 19.15.17.11 NMAC	•
Temporary: Drilling Workover	
Permanent Emergency Cavitation P&A	
Lined Unlined Liner type: Thicknessmil LLDPE	HDPE PVC Other
☐ String-Reinforced	
Liner Seams: Welded Factory Other	Volume:bbl Dimensions: L x Wx D
3. Closed-loop System: Subsection H of 19.15.17.11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling intent) Drying Pad Above Ground Steel Tanks Haul-off Bins Other Lined Unlined Liner type: Thickness mil LLDP! Liner Seams: Welded Factory Other	HDPE PVC Other
Selow-grade tank: Subsection I of 19.15.17.11 NMAC Volume: 120	inch lift and automatic overflow shut-off sidewalls, vaulted, automatic high-level shut off, no liner
5.	
Alternative Method:	
Submittal of an exception request is required. Exceptions must be submitted to	o the Santa Fe Environmental Bureau office for consideration of approval.

-6.	
Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks)	
Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, institution or church)	hospital,
Four foot height, four strands of barbed wire evenly spaced between one and four feet	•
Alternate. Please specify Four foot height, steel mesh field fence (hogwire) with pipe top railing	
7. Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)	
☐ Screen ☐ Netting ☒ Other Expanded metal or solid vaulted top	
Monthly inspections (If netting or screening is not physically feasible)	
intolainy inspections (it fleating of screening is not physically feasible)	
Signs: Subsection C of 19.15.17.11 NMAC	
12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers	
Signed in compliance with 19.15.3.103 NMAC	
Administrative Approvals and Exceptions:	
Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank:	
Administrative approval(s): Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau of	office for
consideration of approval.	
Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	
10. Siting Criteria (regarding permitting): 19.15.17.10 NMAC	
Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accep	table source
material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appro office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of a	
Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to dryi	
above-grade tanks associated with a closed-loop system.	
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ⊠ No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa	☐ Yes ⊠ No
lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.	☐ Yes ⊠ No
(Applies to temporary, emergency, or cavitation pits and below-grade tanks)	□ NA
- Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	D. D.
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to permanent pits)	☐ Yes ☐ No ☑ NA
- Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock	☐ Yes ⊠ No
watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance	☐ Yes ⊠ No
adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	
Within 500 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☑ No
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☑ No
Within an unstable area.	☐ Yes ⊠ No
 Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map 	
Within a 100-year floodplain.	☐ Yes ⊠ No

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number:
12.
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) API Number:
Previously Approved Operating and Maintenance Plan API Number: (Applies only to closed-loop system that use
above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Proposed Closure: 19.15.17.13 NMAC
Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan. Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System Alternative Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench-Burial Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. □ Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC □ Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC □ Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) □ Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC □ Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC

Form C-144 Oil Conservation Division Page 3 of 5

Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: (19.15.17.13.1 Instructions: Please indentify the facility or facilities for the disposal of liquids, drilling fluids and drill cuttings. Use attachment if facilities are required.										
Disposal Facility Name: Disposal Facility Permit Number:	·									
Disposal Facility Name: Disposal Facility Permit Number:										
Will any of the proposed closed-loop system operations and associated activities occur on or in areas that will not be used for future service and operations? Yes (If yes, please provide the information below) No										
Required for impacted areas which will not be used for future service and operations: Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC										
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable sour provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate dist considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Justi demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	rict office or may be									
Ground water is less than 50 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA									
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA									
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA									
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No									
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image										
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	☐ Yes ☐ No									
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No									
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No									
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No									
Within an unstable area. - Engineering measures incorporated into the design; NM Burcau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☐ No									
Within a 100-year floodplain FEMA map	☐ Yes ☐ No									
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19.15.17.11 NMAC Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19. Protocols and Procedures - based upon the appropriate requirements of 9.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC	15.17.11 NMAC									

		·
Operator Application Certification: I hereby certify that the information submitted with this application is true,	accurate and complete to	the best of my knowledge and belief.
Name (Print): Kim Champlin	Title:	Environmental Representative
Signature: Kim Champlin	Date:	02/02/2009
e-mail address: kim_champlin@xtoenergy.com	Telephone:	(505) 333-3100
20.		
OCD Approval: Permit Application (including closure plan) OCD Representative Signature:	- Conetto	Approval Date: 5/4/11
Title: Environmental Engineer Com	Plance O OCD Permit Num	ther:
21. Closure Report (required within 60 days of closure completion): Subseinstructions: Operators are required to obtain an approved closure plan p. The closure report is required to be submitted to the division within 60 day section of the form until an approved closure plan has been obtained and in the control of the form until an approved closure plan has been obtained and the control of the form until an approved closure plan has been obtained and the control of the form until an approved closure plan has been obtained and the control of the form until an approved closure plan has been obtained and the control of the form until an approved closure plan has been obtained and the control of the form until an approved closure plan has been obtained and the control of the form until an approved closure plan p.	orior to implementing any os of the completion of the the closure activities have	closure activities and submitting the closure report. closure activities. Please do not complete this
Closure Method: Waste Excavation and Removal On-Site Closure Method A If different from approved plan, please explain.	lternative Closure Method	d Waste Removal (Closed-loop systems only)
23. Closure Report Regarding Waste Removal Closure For Closed-loop Systemstructions: Please indentify the facility or facilities for where the liquidation facilities were utilized.		
Disposal Facility Name:	Disposal Facility l	Permit Number:
Disposal Facility Name:	Disposal Facility I	Permit Number:
Were the closed-loop system operations and associated activities performed Yes (If yes, please demonstrate compliance to the items below)	on or in areas that will no	
Required for impacted areas which will not be used for future service and of Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique	perations:	•
24.		
	WAZARDO,	NAD: 1927 1983
25. Operator Closure Certification:	16, 2016	
I hereby certify that the information and attachments submitted with this clobelief. I also certify that the closure complies with all applicable closure req	sure report is true, second	e and complete to the best of my knowledge and specified in the approved closure plan.
		S Supervisor
Signature:	Date:	6/24/11
e-mail address: James - Mc Daniel Oxtoeneray.c	Telephone:	<i>5</i> 05-333-3701

District I 1625 N. French Dr , Hobbs, NM 88240 1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

			Rele	ease Notific	catio	n and Co	orrective A	ction					
						OPERA	ГOR		al Report	\boxtimes	Final Report		
Name of Co	mpany: X	TO Energy,	Inc.			Contact: James McDaniel							
		00, Aztec, N				Telephone No.: (505) 333-3701							
Facility Nar	ne: RP Ha	rgrave M#1	(30-045-	30148)		Facility Typ	e: Gas Well (Pi	ctured Cliffs)					
Surface Ow	ner: Feder	 al		Mineral C)wner:			Lease 1	No.:				
						VOEDE	. E A CIE						
Unit Letter	Section	T1.1.	T D			N OF RE	·	East/West Line	Country				
C	9	Township 27N	Range 10W	Feet from the 660	North	/South Line FNL	Feet from the 1980	FWL	County San Juan				
Latitude: 36.5949 Longitude: -107.9027													
				NAT	URE	OF REL	EASE						
Type of Rele	ase: None						Release: NA		Recovered:				
Source of Re				<u> </u>			Hour of Occurrence	e: NA Date and	Hour of Dis	covery	: NA		
Was Immedia	ate Notice (] Yes [No Not Re	equired	If YES, To	Whom?						
By Whom?						Date and I							
Was a Water	course Read	ched?] Yes ⊠] No		If YES, Vo	olume Impacting t	the Watercourse.					
If a Watercou	ırse was Im	pacted, Descr	ibe Fully.	k									
The below g sample was c and BTEX vi	rade tank wollected be a USEPA N	neath the loca Method 8021,	of service a tion of the and for to	at the RP Hargrav on-site BGT, and	l submi sample	tted for labora returned resi	itory analysis for	nd abandoning of th TPH via USEPA N t Rule' spill confirr	1ethod 418.1	and 80	015, benzene		
		and Cleanup / firmed for this											
regulations a public health should their or the environ	II operators or the envi operations I nment. In a	are required to a ronment. The nave failed to a	to report and acceptant adequately OCD accep	nd/or file certain r ce of a C-141 report investigate and r	elease r ort by the emedia	notifications a se NMOCD m te contaminat	nd perform correct parked as "Final Rition that pose a thr	inderstand that pur- ctive actions for rel eport" does not rel cat to ground wate responsibility for c	eases which ieve the oper r, surface wa	may er rator of ater, hu	ndanger f liability man health		
	//	16) -	/			OIL CON	SERVATION	DIVISIO	<u>N</u>			
Signature: Printed Name	e: James M	cDaniel, CHM	/ 1M #1567	<u>/</u> 6		Approved by District Supervisor:							
Title: EH&S						Approval Date: Expiration Date:							
E-mail Addre	ess: James	McDaniel@x	toenergy.c	om		Conditions of Approval: Attached				. 🗆			

Phone: 505-333-3701

Date: 6/24/2011 * Attach Additional

XTO Energy Inc. San Juan Basin Below Grade Tank Closure Report

Lease Name: RP Hargrave M #1

API No.: 30-045-30148

Description: Unit C, Section 9, Township 27N, Range 10W, San Juan County

In accordance with Rule 19.15.17.13 NMAC the following information describes the closure requirements of below-grade tanks on XTO Energy Inc. (XTO) locations. This is XTO's standard procedure for all below-grade tanks. A separate plan will be submitted for any below-grade tank which does not conform to this plan.

General Plan

1. XTO will close below-grade tanks within the time periods provided in 19.15.17.13 NMAC, or by an earlier date that the division requires because of imminent danger to fresh water, public health or the environment.

Closure Date is February 14, 2011

2. XTO will close a below-grade tank that does not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC or is not included in Paragraph (5) of Subsection I of 19.15.17.11 NMAC within five years after June 16, 2008, if not retrofitted to comply with Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC.

Closure Date is February 14, 2011

3. XTO will close a permitted below-grade tank within 60 days of cessation of the below-grade tank's operation or as required by the transitional provisions of Subsection B of 19.15.17.17 NMAC in accordance with a closure plan that the appropriate division district office approves. The closure report will be filed on form C-144.

Required C-144 Form is attached to this document.

4. XTO will remove liquids and sludge from below-grade tanks prior to implementing a closure method and will dispose of the liquids and sludge in a division-approved facility. Approved facilities and waste streams include:

Envirotech Permit No. NM01-0011 and IEI Permit No. NM 01-0010B

Soil contaminated by exempt petroleum hydrocarbons

Produced sand, pit sludge and contaminated bottoms from storage of exempt wastes

Basin Disposal Permit No. NM01-005

Produced water

All liquids and sludge were removed from the tank prior to closure activities.

5. XTO will remove the below-grade tank and dispose of it in a division approved facility or recycle, reuse, or reclaim it in a manner that the appropriate division district office approves. XTO has removed the below grade tank, and will dispose of it at a division approved facility, or recycle, reclaim or reuse it in a manner that is approved by the division.

6. XTO will remove any on-site equipment associated with a below-grade tank unless the equipment is required for some other purpose.

All equipment has been removed due to the plugging and abandoning of the RP Hargrave M #1 well site.

At a minimum 5 point composite sample will be collected along with individual grab samples from any area that is wet, discolored or showing other evidence of a release. Samples will be analyzed for BTEX, TPH and chlorides to demonstrate that the benzene concentration, as determined by EPA SW-846 methods 8021B or 8260B or EPA method that the division approves, does not exceed 0.2 mg/kg; total BTEX concentration, as determined by EPA SW-846 methods 8021B or 8260B or other EPA method that the division approves, does not exceed 50 mg/kg; the TPH concentration, as determined by EPA method 418.1 or other EPA method that the division approves, does not exceed 50 mg/kg; and the chloride concentration, as determined by EPA method 300.1 or other EPA method that the division approves, does not exceed 250 mg/kg, or the background concentration, whichever is greater. XTO will notify the division of its results on form C-141.

A five point composite sample was taken of the pit using sampling tools and all samples tested per Subsection B of 19.15.17.1 3(B)(1)(b). (Sample results attached).

Components	Test Method	Limit (mg/Kg)	Results
Benzene	EPA SW-846 8021B or 8260B	0.2	BDL mg/kg
BTEX	EPA SW-846 8021B or 8260B	50	BDL mg/kg
TPH	EPA SW-846 418.1	100	31 mg/kg
Chlorides	EPA 300.1	250 or background	25 mg/kg

8. If XTO or the division determines that a release has occurred, XTO will comply with 19.15.3.116 NMAC and 19.15.1.19NMAC as appropriate.

All results are below the 'Pit Rule' spill confirmation standards, confirming that a release has not occurred.

9. If the sampling program demonstrates that a release has not occurred or that any release does not exceed the concentrations specified in Paragraph (4) of Subsection E of 19.15.17.13 NMAC, XTO will backfill the excavation with compacted, non-waste containing, earthen material; construct a division prescribed soil cover; recontour and re-vegetate the site.

The pit cellar was backfilled using compacted, non-waste containing earthen material, with a division prescribed soil cover.

- 10. Notice of Closure operations will be given to the Aztec Division District III office between 72 hours and one week prior to the start of closure activities via email or verbally.

 The notification will include the following:
 - i. Operator's name
 - ii. Well Name and API Number
 - iii. Location by Unit Letter, Section, Township, and Range

Notification was provided to Mr. Brandon Powell with the Aztec office of the OCD via email on February 9, 2011; see attached email printout.

The surface owner shall be notified of XTO's proposal to close the BGT as per the approved closure plan using certified mail, return receipt requested.

The surface owner was notified on February 10, 2011; see attached letter and return receipt.

11. Re-contouring of location will match fit, shape, line, form and texture of the surrounding area. Re-shaping will include drainage control, prevent ponding, and prevent erosion. Natural drainages will be unimpeded and water bars and/or silt traps will be placed in areas where needed to prevent erosion on a large scale. Final re-contour shall have a uniform appearance with smooth surface, fitting the natural landscape.

The site has been recontoured to match the above mentioned specifications.

12. A minimum of 4 feet of cover shall be achieved and the cover shall include 1 foot of suitable material to establish vegetation at the site, or the background thickness of topsoil, whichever is greater.

The site has been backfilled to match these specifications.

13. XTO will seed the disturbed areas the first growing season after the operator closes the pit. Seeding will be accomplished via drilling on the contour whenever practical or by other division-approved methods. BLM or Forest Service stipulated seed mixes will be used on federal lands. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintain that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs.

The location has been reclaimed pursuant to the BLM MOU.

- 14. All closure activities will include proper documentation and be available for review upon request and will be submitted in closure report form to OCD within 60 days of closure of the below-grade tank. Closure report will be filed on form C-144 and incorporate the following:
 - i. Proof of closure notice to division and surface owner; attached
 - ii. Details on capping and covering, where applicable; per OCD Specifications
 - iii. Inspection reports; None Found
 - iv. Confirmation sampling analytical results; attached
 - v. Disposal facility name(s) and permit number(s); see above
 - vi. Soil backfilling and cover installation; per OCD Specifications
 - vii. Re-vegetation application rates and seeding techniques, (or approved alternative to re-vegetation requirements if applicable); **per the BLM MOU**
 - viii. Photo documentation of the site reclamation. attached
- 15. This closure report is being submitted after the 60 day deadline required by the 'Pit Rule' due to a unforeseen delay on final reclamation of this well site. This delay was due to the pipeline riser not being removed by the gathering company in a timely fashion.



COVER LETTER

Monday, January 17, 2011

James McDaniel XTO Energy 382 County Road 3100 Aztec, NM 87410

TEL: (505) 787-0519 FAX (505) 333-3280

RE: RP Hargrave M #1

Dear James McDaniel:

Order No.: 1101386

Hall Environmental Analysis Laboratory, Inc. received 1 sample(s) on 1/13/2011 for the analyses presented in the following report.

This report is a revised report and it replaces the original report issued January 17, 2011.

No determination of compounds below these (denoted by the ND or < sign) has been made.

Reporting limits are determined by EPA methodology.

Please don't hesitate to contact HEAL for any additional information or clarifications.

Sincerely,

Andy Freeman, Laboratory Manager

NM Lab # NM9425 AZ license # AZ0682 ORELAP Lab # NM100001 Texas Lab# T104704424-08-TX



Hall Environmental Analysis Laboratory, Inc.

Date: 17-Jan-11

CLIENT:

XTO Energy

Client Sample ID: BGT Closure Comp

Lab Order:

1101386

Collection Date: 1/11/2011 3:10:00 PM

Project:

RP Hargrave M #1

Date Received: 1/13/2011

Lab ID:

1101386-01

Matrix: SOIL

Analyses	Result	PQL Qu	al Units	DF	Date Analyzed
EPA METHOD 418.1: TPH					Analyst: JB
Petroleum Hydrocarbons, TR	31	20	mg/Kg	1	1/17/2011

Qualifiers:

- * Value exceeds Maximum Contaminant Level
- E Estimated value
- J Analyte detected below quantitation limits
- NC Non-Chlorinated
- PQL Practical Quantitation Limit

- B Analyte detected in the associated Method Blank
- H Holding times for preparation or analysis exceeded
- MCL Maximum Contaminant Level
- ND Not Detected at the Reporting Limit
- S Spike recovery outside accepted recovery limits

Date: 17-Jan-11

QA/QC SUMMARY REPORT

Client:

XTO Energy

Project:

RP Hargrave M #1

Work Order:

1101386

Analyte	Result	Units	PQL	SPK Va SP	K ref	%Rec L	owLimit Hig	ghLimit	%RPD	RPDLimit	Qual
Method: EPA Method 418.1: Sample ID: MB-25237	ТРН	MBLK				Batch ID:	25237	Analys	is Date:		1/17/2011
Petroleum Hydrocarbons, TR Sample ID: LCS-25237	ND	mg/Kg LCS	20			Batch (D:	25237	Analys	is Date:		1/17/2011
Petroleum Hydrocarbons, TR Sample ID: LCSD-25237	105,2	mg/Kg LCSD	20	100	0	105 Batch ID:	86.8 25237	116 Analys	is Date.		1/17/2011
Petroleum Hydrocarbons, TR	106.6	mg/Kg	20	100	0	107	86.8	116	1.36	16.2	

Qualifiers:

E Estimated value

J Analyte detected below quantitation limits

ND Not Detected at the Reporting Limit

H Holding times for preparation or analysis exceeded

NC Non-Chlorinated

R RPD outside accepted recovery limits

#f		Date:											//	Date	☐ EDD (Type)	U NECAT	Accreditation	Standard	QA/QC Package	email or Fax#:	Phone #:		Mailing Address:		C C C	C. C.
ecessary,	1100	Or's	Time:										15:10	Time	Type)_	7	tion	ard	:" <i>[</i>		3)	17	ddress		XTO	nain
samples sub) Jun	Relinguished by	Relinquished										50,1	Matrix		□ Other] ?			5	505) -	Azde	382			of-Cu
If necessary, samples submitted to Hall Environmental may be subcontracted to other	Muster Weeder	A STATE OF THE STA	1										BGT Closure	Sample Request ID				☐ Level 4 (Full Validation)			505		Rd 3100	00	Energy	Chain-of-Custody Record
hay be subc			`										Comp.	st ID				dation)	8	Service						d
ontracted to other a		Must	Received by:										1-402	Container Type and #	Sample Temperature	Orfice	Sampler:	٥٥	1	Project Mana		Project #:	RP Hargrave	rioject name:	Standard	Tum-Around Time:
coredited laboratories.		Les W. m.											Cool	Preservative Type	etature	3 400	J. Mc	James M		ger:					□ Rush	Time:
es. This serves as notice of this poo	1/B////23	=	Date Time									-	1	17.8. V.11.1.		(1) (A)	meganel	mc Daniel					3	k -		
is possi	<u> </u>	<u> </u>	Rer							 		 		BTEX + MT	WAI BE	18201 + T	MB'	s (80)21)		J				
ssibility. Any sub-contracted data will be clearly notated on the analytical report.			Remarks:											BTEX + MTE	3E	+ T	PH.	(Gas	on	ly)		Ę	49(20		
my sub					_		_					 		TPH Method				as/L	Dies	el)		Tel. 505-345-3975	4901 Hawkins NE			
contra			ļ	\dashv	_					_			×	TPH (Metho								γ. 4.	₩ Kin	≤	> :	I
cted d			}	_		-	_		_	 	-		_	EDB (Metho						, , , , , , , , , , , , , , , , , , ,		-397	s NE	www.hallenvironmental.com	NA	
ata wil			-		_								1	8310 (PNA c			1)	<u>.</u>		_	Analysis	Οί	1	halle	5	
be cle			ŀ		\dashv	-		\dashv		 				RCRA 8 Met Anions (F,Cl		_	<u>ـــــ</u>	P∩.	90		alysi	F 29	buc	n⊻iro Tiro	SISA	TI Z
early n			-		\dashv	\dashv	\dashv						\vdash	8081 Pestici						4/	s Re	50	luerc	ňme	ទ	5
otated			}	\dashv	\dashv		\dashv		\dashv	 				8260B (VOA				- CI	33		que	5-34	lle.	ntal.	5	Į
on the			}	\dashv	+	+	\dashv			 			\vdash	8270 (Semi-		 A)			-	48	Request	Fax 505-345-4107	Albuqueraue, NM 87109	3	LABORATOR	ENVIRONMENTA
analyt			ł	\dashv	1	\dashv	-		-	 				3 (-2		-7						07	7109		77 :	Z
章 						_	1	\dashv													137	,	v		A :	ä
ρŗ			Ī	1		\neg	1													\$ \$					9	7

Air Bubbles (Y or N)



12065 Lebanon Rd Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D. 62-0814289

Est. 1970

James McDaniel XTO Energy - San Juan Division 382 Road 3100 Aztec, NM 87410

Report Summary

Tuesday January 18, 2011

Report Number: L497230 Samples Received: 01/13/11 Client Project:

Description: RP Hargrave M 1

The analytical results in this report are based upon information supplied by you, the client, and are for your exclusive use. If you have any questions regarding this data package, please do not hesitate to call.

Entire Report Reviewed By:

Daphne Richards , ESC Representative

Laboratory Certification Numbers

A2LA - 1461-01, AIHA - 100789, AL - 40660, CA - I-2327, CT - PH-0197, FL - E87487 GA - 923, IN - C-TN-01, KY - 90010, KYUST - 0016, NC - ENV375/DW21704, ND - R-140 NJ - TN002,NJ NELAP - TN002, SC - 84004, TN - 2006, VA - 00109, WV - 233 AZ - 0612, MN - 047-999-395, NY - 11742, WI - 998093910, NV - TN000032008A, TX - T104704245, OK-9915

Accreditation is only applicable to the test methods specified on each scope of accreditation held by ESC Lab Sciences

Note \cdot The use of the preparatory EPA Method 3511 is not approved or endorsed by the CA ELAP

The use of the preparatory are section 3511 15 not approved of chaotises 5, the critical

This report may not be reproduced, except in full, without written approval from ESC Lab Sciences Where applicable, sampling conducted by ESC is performed per guidance provided in laboratory standard operating procedures. 060302, 060303, and 060304.



YOUR LAB OF CHOICE

12065 Lebanon Rd Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D 62-0814289

Est. 1970

REPORT OF ANALYSIS

January 18,2011

James McDaniel XTO Energy - San Juan Division 382 Road 3100 Aztec, NM 87410

ESC Sample # . L497230-01

Date Received · January 13, 2011
Description · RP Hargrave M 1

Site ID : RP HARGRAVE M1

Sample ID : BGT CLOSURE COMPOSITE

Project # :

Collected By : James McDaniel Collection Date : 01/11/11 15:10

Parameter	Dry Result	Det. Limit	Units	Method	Date	D11.
Chloride	25.	11.	mg/kg	9056	01/17/11	1
Total Solids	87.6		8	2540G	01/14/11	1
Benzene	BDL	0.0028	mg/kg	8021/8015	01/14/11	5
Toluene	BDL	0.028	mg/kg	8021/8015	01/14/11	5
Ethylbenzene	BDL	0.0028	mg/kg	8021/8015	01/14/11	5
Total Xylene	BDL	0.0086	mg/kg	8021/8015	01/14/11	5
TPH (GC/FID) Low Fraction	BDL	0.57	mg/kg	GRO	01/14/11	5
Surrogate Recovery-%						
a,a,a-Trifluorotoluene (FID)	102		% Rec.	8021/8015	01/14/11	5
a,a,a-Trifluorotoluene(PID)	102		% Rec.	8021/8015	01/14/11	5
TPH (GC/FID) High Fraction Surrogate recovery(%)	5.7	4.6	mg/kg	3546/DRO	01/13/11	1
o-Terphenyl	78.5		% Rec	3546/DRO	01/13/11	1

Results listed are dry weight basis BDL - Below Detection Limit Det Limit - Practical Quantitation Limit(PQL)

Note:
This report shall not be reproduced, except in full, without the written approval from ESC.
The reported analytical results relate only to the sample submitted
Reported: 01/18/11 10:18 Printed: 01/18/11 10:19

Summary of Remarks For Samples Printed 01/18/11 at 10.19·28

TSR Signing Reports. 288 R5 - Desired TAT

No Energy fee. Charge \$10 Shipping Fee per Dave V 1/4/10 When transfering TS to a new dash # DO NOT charge a fee

Sample: L497230-01 Account: XTORNM Received: 01/13/11 09:00 Due Date: 01/20/11 00:00 RPT Date: 01/18/11 10:18



YOUR LAB OF CHOICE

XTO Energy - San Juan Division James McDaniel 382 Road 3100

Aztec, NM 87410

12065 Lebanon Rd Mt. Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D. 62-0814289

Est 1970

Quality Assurance Report Level II

L497230

January 18, 2011

		Labo	oratory Bl	ank					
Analyte	Result		ıts	% Rec	Limit	Ва	Batch Da		
Benzene	< .0005	mg,	/kq			WG	517200 01	/14/11 02:1	
Ethylbenzene	< .0005	mg,				WG	517200 01	/14/11 02.1	
Toluene	< 005	mq						/14/11 02:1	
TPH (GC/FID) Low Fraction	< .1	mg,						/14/11 02 1	
Total Xylene	< .0015	mg,						/14/11 02.1	
a,a,a-Trifluorotoluene(FID)			Rec	101.6	59-128		1/14/11 02		
	.* .	. % I		102.0	54-144			/14/11 02:1	
TPH (GC/FID) High Fraction	< 4	ppr	n			WG	516938 01	/13/11 20 1	
o-Terphenyl	Jul.	% I	Rec.	91 54	50-150	WG	/13/11 20 1		
Total Solids	< .1	ało				WG	/14/11 10·1		
Chloride	< 10	mg,	/kg		,	WG	517474 01	/17/11 10 2	
			Duplicate						
Analyte	Units	Result	Duplic	ate RPD	Limit	R	Ref Samp		
Total Solids	8	92 0	91 4	0.725	5	L	497259-01	WG51710	
		Laborate	ory Contro	l Sample					
Analyte	Units	Known V	Val	Result	% Rec	Li	Limit		
Benzene	mg/kg	.05		0 0528	106.	76	76-113		
Ethylbenzene	mg/kg	. 05		0 0548	110	78	-115	WG51720	
Toluene	mg/kg	. 05		0 0545	109	76	-114	WG51720	
Total Xylene	mg/kg	.15		0.171	114.	81	81-118		
a,a,a-Trifluorotoluene(PID)	· ·				100.8	54	-144	WG51720	
TPH (GC/FID) Low Fraction	mg/kg	5 5		6 35	115.	67	67-135		
a,a,a-Trifluorotoluene(FID)				*	93 07	59	59-128		
TPH (GC/FID) High Fraction	ppm	60		49.4	82 3	50	-150	WG51693	
o-Terphenyl					78.28	. 50	-150	WG51693	
Total Solids	ક	50		50.0	100.	. 85	-115 .	WG51710	
Chloride	mg/kg	200		202	101.	85	85-115		
	L	aboratory Co	ontrol Sam	ple Duplicate	.				
Analyte	Units		Ref	%Rec	Limit	RPD	Limit	Batch	
Benzene			0.0528	107.	76-113	1 10	20	WG51720	
Ethylbenzene	mg/kg	0.0539	0.0548	108	78-115	1 52	20	WG51720	
Toluene			0.0545	107.	76-114	1.52	20	WG51720	
Total Xylene	mg/kg	0.168	0.171	112.	81-118	2 00	20	WG51720	
a,a,a-Trifluorotoluene(PID)				100 4	54-144			WG51720	
TPH (GC/FID) Low Fraction	mg/kg	6.28	6.35	114.	67-135	1 02	20	WG51720	
a,a,a-Trifluorotoluene(FID)				92.50	59-128			WG51720	
TPH (GC/FID) High Fraction	ppm	49.3	49 4	82 0	50-150	0,301 .	20	WG51693	
o-Terphenyl				78.54	50-150			WG51693	

Performance of this Analyte is outside of established criteria

For additional information, please see Attachment A 'List of Analytes with QC Qualifiers '



YOUR LAB OF CHOICE

12065 Lebanon Rd 12065 Lebanon Rd Mt. Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I.D 62-0814289

Est. 1970

XTO Energy - San Juan Division James McDaniel 382 Road 3100

Aztec, NM 87410

Quality Assurance Report Level II

L497230

January 18, 2011

Analyte	Units	Result	y Contro Ref	l Sample Dupl %Rec	ıçace;	Limit	RPD	Limit	Batch
Chloride The Company of the Chloride	mg/kg	2Ó0.	202.	,100	Ł .	85-115", 15	0.995	, ° 20.	₩G51747
			Matrix	Spike					
Analyte	Units	MS Res	Ref	Res TV	% Rec	Limit		Ref Samp	Batch
Benzene	mg/kg	. 0,209	0 ,	.05	83.7	32-137	*	'L497189-01	WG51720
Ethylbenzene	mq/kq	0 220	0 ~	05	88.0	10-150		L497189-01	WG51720
Toluene	mg/kg	0 207	0	05	82 8	20-142		L497189-01	WG51720
Total Xylene	mg/kg	0 688	0	.15	91 7	16-141		L497189-01	WG51720
a,a,a-Trifluorotoluene (PID)		*			99 13	54-144			WG51720
TPH (GC/FID) Low Fraction	mg/kg	23.9	0	5.5	86 9	55-109		L497189-01	WG51720
a,a,a-Trifluorotoluene(FID)		· .	. ×	* * * * *	92.96	59-128	• • •		WG51720
TPH (GC/FID) High Fraction	ppm	53.0	1 97	. 60	85 1 . 79 03	50-150 50-150	٠,	L497096-03	WG51693 WG51693
		Mat	rix Spik	e Duplicate					
Analyte	Units	MSD	Ref	%Rec	Limit	RPD	Limit	Ref Samp	Batch
Benzene Caraca C	mg/kg	0.202	0 209	80.8	32-137	3.50 ∦	39 ;	L497189-01;	WG51720
Ethylbenzene	mg/kg	0.211	0 220	84.3	10-150	4 36	44	L497189-01	WG51720
Toluene	mg/kg	0.197	0.207	78 6	20-142	5.17	42	L497189-01	WG51720
Total Xylene'	mg/kg	0.654	0 688		16-141	5,01 /	46	L497189-01	WG51720
a,a,a-Trifluorotoluene(PID)	3 / 1.19			99 65	54-144				WG51720
TPH (GC/FID) Low Fraction	mg/kg	24 1	23 9	87.7	55-109	0.938	20	L497189-01	WG51720
a,a,a-Trifluorotoluene(FID)	. 15		,	91 60 -	59-128		•		WG51720
TPH (GC/FID) High Fraction	ppm	54 0	53.0	86.7	50-150	1.79	20	L497096-03	WG51693
o-Terphenyl									

Batch number /Run number / Sample number cross reference

WG517200: R1537389. L497230-01 WG516938 R1537449 L497230-01 WG517101 R1538451 L497230-01 WG517474 R1541529: L497230-01

 ^{*} Calculations are performed prior to rounding of reported values
 * Performance of this Analyte is outside of established criteria
 For additional information, please see Attachment A 'List of Analytes with QC Qualifiers '



YOUR LABOF CHOICE

XTO Energy - San Juan Division James McDaniel 382 Road 3100

Aztec, NM 87410

Quality Assurance Report Level II

L497230

January 18, 2011

12065 Lebanon Rd. Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D 62-0814289

Est 1970

The data package includes a summary of the analytic results of the quality control samples required by the SW-846 or CWA methods. The quality control samples include a method blank, a laboratory control sample, and the matrix spike/matrix spike duplicate analysis. If a target parameter is outside the method limits, every sample that is effected is flagged with the appropriate qualifier in Appendix B of the analytic report.

Method Blank - an aliquot of reagent water carried through the entire analytic process The method blank results indicate if any possible contamination exposure during the sample handling, digestion or extraction process, and analysis. Concentrations of target analytes above the reporting limit in the method blank are qualified with the "B" qualifier.

Laboratory Control Sample - is a sample of known concentration that is carried through the digestion/extraction and analysis process. The percent recovery, expressed as a percentage of the theoretical concentration, has statistical control limits indicating that the analytic process is "in control". If a target analyte is outside the control limits for the laboratory control sample or any other control sample, the parameter is flagged with a "J4" qualifier for all effected samples

Matrix Spike and Matrix Spike Duplicate - is two aliquots of an environmental sample that is spiked with known concentrations of target analytes. The percent recovery of the target analytes also has statistical control limits. If any recoveries that are outside the method control limits, the sample that was selected for matrix spike/matrix spike duplicate analysis is flagged with either a "J5" or a "J6". The relative percent difference (%RPD) between the matrix spike and the matrix spike duplicate recoveries is all calculated. If the RPD is above the method limit, the effected samples are flagged with a "J3" qualifier.

Company Name/Address			Alternate Bi	lling				Analysis/Container/Preservative					Chain of Custody
XTO Energy, Inc.									, E				C026 Page_of_
	ATORNMU31810										1		
382 County Road 3100													Prepared by
Aztec, NM 87410	•												
							İ	_					ENVIRONMENTAL
							_	0	in				Science corp
			Report to Jam	es McDaniel			ال ال	$\mathbb{L}^{\mathcal{Q}}$					12065 Lebanon Road
					doenergy.com	_,	0	70	- 3				Mt. Juliet TN 37122
Project Pescripion: 1444 Vava	#1	Grty/State Collected.			1/20	2	7		,		Phone (615)758-5858		
PHONE 505-333-3701	Client Project I	No.	 	Lab Project #	71011		3		30	"			Phone (800) 767-5859
FAX:					_		1	2	17				. FAX (615)758-5859
Collected by James McDaniel	Site/Facility ID	rarmu	4 M#1	PO#				8015					CoCode (lab use only)
Collected by(signature)	Rush? (L	ab MUST b	e Notified)	Date Result	ts Needed	No	609	12	\ \ \	-			XTORNM
		Next Day				140	18	2	6				Template/Prelogin
4///		WO Day		Email? N	lo X Yes	of		3	rio		1		Tempator Gogii
Packed on Ice N Y		hree Day .			loYes		$ \hat{\mu} $	3	0	į			Shipped Via Fed Ex
Sample ID	Comp/Grd.	Matrix	Depth	Date	Time	Cntrs	BTEX	DRO/GRO	Chle	Ę.	1	6.4	y
BGT Closure Composite		SS	Depth	1/11/11	1500	 	X	X	X	* *	<u>.</u>	+	
DG 1 Closore Composite	Comp	<u> </u>		7 11///	15	+ \	7	<u> </u>			*	₹. ₩.\$`	LY9773021
						↓	<u> </u>		έ.			48 S	
		<u>.</u>		1		Ì	31 11 %				ł		
							1		,				
					 	<u> </u>			× .	-	1	1	
						 	\vdash	-	-	-	-	 	
			<u> </u>		 	-	<u> </u>		7.03	- 62	٢_	+	
						<u> </u>	<u> </u>		\$0	8.			
								1	480	i A			
									***	W.	Š	7.1	
		L		<u> </u>	<u>1</u>	.1	<u> </u>	L		1_8/43	56		<u> </u>
Matrix SS-Soil/Solid GW-Groundwar	ter WW-Wa	stewater D	W-Drinking W	Vater OT-O	ther							pH	Temp
Remarks											F	low	Other
Relinquiene by Signature	Date	1333	Received by.(S	ignature)	MA					FedEx_X_	UPS_	Other	Condition (lab use only)
11/1/	1/12/11		<u> </u>		メット			++	021				Cocs1
Refinquisher by (Signature	Date:	Time	Received by, (S	Signature)	3.1		Temp 3.4	į.		Bött	les Rec	erved: ^~ 02 %	
Relinquisher by:(Signature	Date	Time	Received for la	ab by (Signatur	e) In A		Date	13/) ₁	Tim	e.	200	pH Checked NCF

を とうない これの あるとう とうない



James McDaniel /FAR/CTOC 02/09/2011 06:26 AM

To brandon.powell@state.nm.us

cc

bcc

Subject R P Hargrave M #1 BGT Closure

Brandon,

Please accept this email as the required notification for BGT closure activities at the R-P Hargrave M #1 well site (api #30-045-30148) located in Unit C, Section 9, Township 27N, Range 10W, San Juan County, New Mexico. This BGT is being closed due to plugging and abandoning of this well location. Thank you for your time in regards to this matter.





February 9, 2011

Mark Kelly, Bureau of Land Management – Farmington Field Office 1235 La Plata Highway Farmington, New Mexico, 87401

Ré: R P Hargrave M #1 API #30-045-30148 Unit C, Section 9, Township 27N, Range 10W, San Juan County, New Mexico


Dear Mr. Kelly,

This submittal is pursuant to Rule 19.15.17.13 requiring operators to notify surface owners of the closure of a below grade tank pit. XTO Energy, Inc. (XTO) is hereby providing written documentation of our proposal to close the below grade tank pit associated with the above mentioned well site by waste excavation and removal.

Should you have questions or require additional information, please feel free to contact me at your convenience at (505) 333-3100. Thank you for your time in regards to this matter.

Respectfully Submitted,

James McDaniel EH&S Specialist XTO Energy, Inc. San Juan Division



SENDER: COMPLETE THIS SECTION Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits. BLM-FFO MARK KELLY 1235 LA PLATA HWY	A. Signature A. Signature A. Signature A. Agent Addressee B. Received by (Printed Name) D. Is delivery address-different from item 1? Yes If YES, enter delivery address below: No
FARMINGTON, NM 87401	3. Service Type ☐ Certified Mail ☐ Express Mail ☐ Registered ☐ Return Receipt for Merchandise ☐ Insured Mail ☐ C.O.D.
	4. Restricted Delivery? (Extra Fee)
2. Article Number (Transfer from service label) 7010 0780	0001 6436 9512
PS Form 3811, February 2004 Domestic Retu	ırn Receipt 102595-02-M-1540

XTO Energy, Inc. RP Hargrave M #1 Section 9, Township 27N, Range 10W Closure Date 2/14/2011




Photo 1: RP Hargrave M #1 after Reclamation (view 1)




Photo 2: RP Hargrave M #1 after Reclamation (view 2)



Well Below Tank Inspection Report

RouteName		StopName		Pumper	Foreman	WellNam	е		APIWellNumber		Section	Range	Township
Below Grade Pit	Forms (Temp	. RP Hargrav	ve M 1	Unassigned	Unassigned	RP HAR	GRAVE N	И 01 (PA)	3004530148		9	10W	27N
InspectorName	Inspection Date	Inspection Time	Visible LinerTears	VisibleTankLeak Overflow	Collection OfSurfaceRun	Vısıble LayerOil	Visible Leak	Freeboard EstFT	PitLocation	PıtType	Notes		
robbie meek	08/29/2008	11:35	No	No	No	No	No	3					
Trent Willis	09/11/2008	13.43	No	No	No	Yes	No	4					
Trent Willis	10/02/2008	09:56	No	No	No	Yes	No	3			Dumpline	e from co	ompressor putting oil in the pit
Trent Willis	11/03/2008	13 59	No	No	No	Yes	No	4	Well Water Pit	Below Ground	Dumpline	e from co	ompressor putting oil in the pit
Trent Willis	01/01/2009	12 00	No	No	No	Yes	No	5	Well Water Pit	Below Ground	Dumpline	e from co	ompressor putting oil in the pit
Trent Willis	02/19/2009	13:45	No	No	No	Yes	No	3	Well Water Pit	Below Ground	Compres		
Trent Willis	03/09/2009	12 33	No	No	No	Yes	No	3	Well Water Pit	Below Ground	Compres	sor oil	
GARY WARD	04/13/2009	11 08	No	No	No	Yes	No	5	Well Water Pit	Below Ground	Compres		
GARY WARD	05/06/2009	14.02	No	No	No	Yes	No	4	Well Water Pit	Below Ground	Compres		
GARY WARD	06/10/2009	13:14	No	No	No	Yes	No	4	Well Water Pit	Below Ground	Compres		
GARY WARD	07/07/2009	14:546	No	No	No	Yes	No	4	Well Water Pit	Below Ground	Compres		
GARY WARD	08/12/2009	10:02	No	No	No	Yes	No	2	Well Water Pit	Below Ground	d Compressor oil		
GARY WARD	09/15/2009	12.18	No	No	No	Yes	No	4	Well Water Pit	Below Ground	d Compressor oil		
GARY WARD	10/27/2009	13.07	No	No	No	Yes	No	3	Well Water Pit	Below Ground	d Compressor oil		
GARY WARD	11/10/2009	16 52	No	No	No	Yes	No	3	Well Water Pit	Below Ground	d Compressor oil		
Trent Willis	12/31/2009	14 20	No	No	No	Yes	No	3	Well Water Pit	Below Ground	Compres	sor oil S	now
Trent Willis	01/23/2010	14 18	No	No	No	Yes	No	2	Well Water Pit	Below Ground	Compres	sor oil S	now
GARY WARD	02/25/2010	11.16	No	No	No	Yes	No	1	Well Water Pit	Below Ground	CALL IN	PIT	
GARY WARD	03/31/2010	11 59	No	No	No	Yes	No	5	Well Water Pit	Below Ground			
Trent Willis	08/05/2010	11.40	No	No	No	Yes	No	5	Well Water Pit	Below Ground	Well to b	e PNA \	Well out of service
GARY WARD	09/15/2010	12 16	No	No	No	Yes	No	5	Well Water Pit	Below Ground	Well to b	e PNA. \	Well out of service
TRENT WILLIS	10/04/2010	14 [.] 25	No	No	No	Yes	No	5	Well Water Pit	Below Ground	Well to b	e PNA \	Well out of service
GARY WARD	12/05/2010	11:24	No	No	No	Yes	No	5	Well Water Pit	Below Ground	Well to b	e PNA. \	Well out of service