

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-039-06721

OPERATOR

X Initial Report Final Report

| | |
|-------------------------------------|----------------------------|
| Name of Company- Noble Energy, Inc. | Contact- Tyson Hutton |
| Address- 1625 Broadway Suite 2200 | Telephone No. 303-228-4238 |
| Facility Name- Tribal C#002 | Facility Type- Gas |

| | | |
|---------------------------------------|---------------|-------------------------|
| Surface Owner- Jicarilla Apache Tribe | Mineral Owner | Lease No. Jicarilla #97 |
|---------------------------------------|---------------|-------------------------|


LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| F | 06 | 26N | 03W | 1650 | North | 1550 | West | |

Latitude 36.518103 Longitude -107.188662

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release: Produced water | Volume of Release: Not known | Volume Recovered: |
| Source of Release: | Date and Hour of Occurrence: Not Known | Date and Hour of Discovery 5/23/2011 |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? N/A | |
| By Whom? N/A | Date and Hour N/A | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. N/A | |



If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Scrubber pit believed to have run over some time in March. Pumper did not follow reporting guidelines and failed to report. Discovered by Jicarilla Nation

Describe Area Affected and Cleanup Action Taken.*
Affected area is approximately 30ftX30ft and 25ft deep Impacted soil of approximately 60 cubic yards has been removed. Soil has been sampled and per request of Jicarilla Nation backfill operations have begun.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|---|-----------------------------------|
| Signature: | OIL CONSERVATION DIVISION | |
| Printed Name: Tyson Hutton | Approved by District Supervisor: | |
| Title: Environmental Specialist | Approval Date: 6/8/11 | Expiration Date: |
| E-mail Address: thutton@nobleenergyinc.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 6/6/2011 Phone: 303-228-4238 | Ensure proper reporting in the future NJK 1122353551 | |

* Attach Additional Sheets If Necessary