

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Shelly Cook-Cowden
Address 3401 E. 30th St., Farmington, NM 87402	Telephone No. 505-324-5140
Facility Name Porkchop Federal 28 No. 1	Facility Type Gas Well API# 3003925965

Surface Owner Federal	Mineral Owner Federal	Lease No. SF - 078048
-----------------------	-----------------------	-----------------------

LOCATION OF RELEASE

Unit Letter A	Section 28	Township 026N	Range 007W	Feet from the 435'	North/South Line North	Feet from the 1180'	East/West Line East	County
------------------	---------------	------------------	---------------	-----------------------	---------------------------	------------------------	------------------------	--------

Latitude 36.464034° N Longitude 107.575717° W

NATURE OF RELEASE

Type of Release – Produced Water	Volume of Release – 26 BBL	Volume Recovered – 25.5 BBL
Source of Release – Production pit tank	Date and Hour of Occurrence – 6/2/11 @ 12:00 PM	Date and Hour of Discovery – 6/2/11 @ 12:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Verbal – Bill Leiss BLM, Mark Kelly BLM & Brandon Powell NMOCD ----Followed by email notification on 6/2/11 @ 4:51 PM	
By Whom? Gwen Frost	Date and Hour – 6/2/11 @ 4:51 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A 26 BBL produced water spill occurred as a result of fatigue on the water pit tank due to corrosion. A crew was on location at this time & a vac truck was mobed to location to recover fluids.

Describe Area Affected and Cleanup Action Taken.* All fluids remained on location within the berm and the vac truck recovered approximately 25.5 BBL of produced water. At the request of the NMOCD the soil will be tested for hydrocarbons.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Shelly Cook-Cowden</i>		OIL CONSERVATION DIVISION	
Printed Name: Shelly Cook-Cowden		Approved by District Supervisor: <i>[Signature]</i>	
Title: Environmental Technician		Approval Date: 6/10/11	Expiration Date:
E-mail Address: Shelly.g.Cook-Cowden@ConocoPhillips.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 9, 2011 Phone: 505-324-5140		WJK1122353281	

* Attach Additional Sheets If Necessary

