

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company <b>Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company</b>	Contact <b>Shelly Cook-Cowden</b>	
Address <b>3401 E. 30<sup>th</sup> St., Farmington, NM 87402</b>	Telephone No. <b>505-324-5140</b>	
Facility Name <b>San Juan 28-6 Unit 185M</b>	Facility Type <b>Gas Well API# 3003927655</b>	
Surface Owner <b>Federal</b>	Mineral Owner <b>Federal</b>	Lease No. <b>NMSF - 079051</b>

#### LOCATION OF RELEASE

Unit Letter <b>M</b>	Section <b>33</b>	Township <b>028N</b>	Range <b>006W</b>	Feet from the <b>1145'</b>	North/South Line <b>South</b>	Feet from the <b>660'</b>	East/West Line <b>West</b>	County <b>Rio Arriba</b>
-------------------------	----------------------	-------------------------	----------------------	-------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude **36.61333 ° N** Longitude **107.47833 ° W**

#### NATURE OF RELEASE

Type of Release - <b>Produced Water</b>	Volume of Release - <b>5 BBL Produced Water</b>	Volume Recovered - <b>0 BBL</b>
Source of Release - <b>Production Tank</b>	Date and Hour of Occurrence - <b>Unknown</b>	Date and Hour of Discovery - <b>6/05/11 @ 8:00 AM</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour -	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* **A small hole developed on the production tank due to corrosion causing produced water to be released onto the ground within the berm.**

Describe Area Affected and Cleanup Action Taken.\* **Separator was shut in and Western called to pull tank. The production tank will be cleaned/inspected and repaired/replaced.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Shelly Cook-Cowden</i>		OIL CONSERVATION DIVISION	
Printed Name: <b>Shelly Cook-Cowden</b>		Approved by District Supervisor: <i>Bob Bell</i>	
Title: <b>Environmental Technician</b>		Approval Date: <i>6/10/11</i>	Expiration Date:
E-mail Address: <b>Shelly.g.Cook-Cowden@ConocoPhillips.com</b>		Conditions of Approval: <i>nJK1122352824</i>	Attached <input type="checkbox"/>
Date: <b>June 9, 2011</b> Phone: <b>505-324-5140</b>			

\* Attach Additional Sheets If Necessary