

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company ConocoPhillips Company	Contact Shelly Cook-Cowden
Address 3401 E. 30th St., Farmington, NM 87402	Telephone No. 505-324-5140
Facility Name: Scott Federal 6N	Facility Type: Gas Well/API # 3003930669

Surface Owner: Federal	Mineral Owner: Federal	Lease No. SF-079035A
-------------------------------	-------------------------------	-----------------------------


LOCATION OF RELEASE

Unit Letter J	Section 17	Township 26N	Range 26N	Feet from the 1500	North/South Line South	Feet from the 2005	East/West Line East	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude: **36.483541 ° N** Longitude: **107.488552 ° W**

NATURE OF RELEASE

Type of Release: Gas	Volume of Release: 275 MCF	Volume Recovered: 0 MCF
Source of Release: Separator	Date and Hour of Occurrence: 5/12/2011 @ 1:00 AM	Date and Hour of Discovery: 5/12/2011 @ 2:45 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Rupture Disk blew out causing approximately 275 MCF to be released to atmosphere. Upon discovery separator was shut in.		
Describe Area Affected and Cleanup Action Taken.* Unit was repaired and put back into service.		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Shelly Cook-Cowden</i>		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Shelly Cook-Cowden		Approved by District Supervisor: <i>Red Bell</i>	
Title: Environmental Technician		Approval Date: 5/23/11	Expiration Date:
E-mail Address: Shelly.g.Cook-Cowden@ConocoPhillips.com		Conditions of Approval: n JK1122355537	Attached <input type="checkbox"/>
Date: May 19, 2011 Phone: 505-324-5140			

* Attach Additional Sheets If Necessary