<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back

Form C-141

Revised October 10, 2003

side of form Santa Fe, NM 87505 **Release Notification and Corrective Action**

						OPERA	ГOR		☐ Initia	al Report		Final Report	
Name of Co		Contact: Courtney Cochran											
Address: 20		Telephone No.: 326-9457											
Facility Name: Hughes A2							Facility Type: natural gas well API # 3				300452334500		
Surface Ow	ner: Feder	Federal			Lease No. SF 078049								
LOCATION OF RELEASE													
Unit Letter B	Section 27	Township T29N	Range R8W	Feet from the 790	North North	/South Line	Feet from the 1460	East/V East	West Line	County: San Juan			
Latitude_36.70176Longitude107.65981													
Type of Release: natural gas NATURE OF RELEASE Volume of Release: 578 MCF of Volume Recovered: no gas recovered													
Type of Release: natural gas							Release: 578 MC	Volume I	Volume Recovered: no gas recovered				
Source of Release: water dump valve							gas Date and Hour of Occurrence: 3/28 6 p.m 3/29 11 a.m. & 3/31 5 a.m 11 a.m.					3/31/2011	
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required							If YES, To Whom? Brandon Powell at the NMOCD and Sherrie Landon at the						
By Whom? Courtney Cochran							Date and Hour: 9:30 a.m. on 4/5/2011						
Was a Watercourse Reached? ☐ Yes ☒ No							If YES, Volume Impacting the Watercourse.						
If a Watercon	ırse was Im	pacted, Descr	ibe Fully.'	k						OIL CONS	. DIV		
							DIST. 3						
Describe Cause of Problem and Remedial Action Taken.* The water dump valve hung open twice on the 250 pentroof separator thereby releasing gas into the atmosphere. The incident was reported to the team leader who then initiated a RCFA and volume calculations. The RCFA indicated equipment instrumentation failure and the proper actions have been taken to correct the issue.													
Describe Area Affected and Cleanup Action Taken.* The gas released dissipated into the atmosphere so no clean-up action was possible.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signature:							OIL CONSERVATION DIVISION						
Printed Name: Courtney Cochran							Approved by District Supervisor:						
Title: Environmental Challenger							e: 4-6-11	Expiration Date:					
E-mail Address: Courtney.Cochran@bp.com						Conditions of Approval:			Attached				
Date: A	pril 5, 2011	[Pł	Phone: 326-9457 N.TK1122141136									

^{*} Attach Additional Sheets If Necessary