

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP	Contact: Courtney Cochran
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 326-9457
Facility Name: Tapp LS 1A	Facility Type: natural gas well API # 300452370000

Surface Owner: Federal	Mineral Owner: Federal	Lease No. NMSF 078499
------------------------	------------------------	-----------------------

LOCATION OF RELEASE

Unit Letter C	Section 22	Township T28N	Range R8W	Feet from the 790	North/South Line North	Feet from the 1560	East/West Line West	County San Juan
------------------	---------------	------------------	--------------	----------------------	---------------------------	-----------------------	------------------------	--------------------

Latitude 36 65196 Longitude 107.67202

NATURE OF RELEASE


Type of Release natural gas	Volume of Release 52 Mcf of gas	Volume Recovered no gas recovered
Source of Release PSV relief on fuel pot	Date and Hour of Occurrence. 2/3/2011 9 am -12 pm 2/3/2011 1pm - 5 pm	Date and Hour of Discovery 2/4/2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully *

Describe Cause of Problem and Remedial Action Taken * PSV relieved on fuel pot twice on 2/3/2011 Possible causes include leak on manual bypass, upstream regulator failure or an issue due to paraffin Well is coded, flagged and tagged PSV will be tested and RCFA will be conducted to determine cause of PSV lift

Describe Area Affected and Cleanup Action Taken *
The gas released dissipated into the atmosphere so no clean-up action was possible

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations



Signature <i>CAG</i>		OIL CONSERVATION DIVISION	
Printed Name Courtney Cochran		Approved by District Supervisor <i>Bob Roll</i>	
Title Environmental Challenger		Approval Date 2/11/11	Expiration Date
E-mail Address Courtney Cochran@bp.com		Conditions of Approval	Attached <input type="checkbox"/>
Date February 8, 2011	Phone 326-9457	NJK 1122335901	

* Attach Additional Sheets If Necessary