

*District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

| | | | |
|-----------------|--|---------------|--------------------------------|
| Name of Company | Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company | Contact | Kelsi Harrington |
| Address | 3401 E. 30th St., Farmington, NM 87402 | Telephone No. | 505-599-3403 |
| Facility Name | San Juan 32-9 Unit 217 | Facility Type | Gas Well API#3004527859 |
| Surface Owner | State | Mineral Owner | State |
| | | Lease No. | E-5382 |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|-----------|------------|------------|---------------|------------------|---------------|----------------|-----------------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| G | 16 | 32N | 09W | 1400' | North | 1555' | East | San Juan |

Latitude 36.98792 ° N Longitude -107.78072 ° W

NATURE OF RELEASE

| | | |
|--|---|--|
| Type of Release – Natural Gas | Volume of Release – 1110 MCF | Volume Recovered – |
| Source of Release: Water Dump Valve | Date and Hour of Occurrence 7/14/2011 4:30 p.m. | Date and Hour of Discovery 7/21/2011 9:15 a.m. |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Brandon Powell (NMOCD)- 7/21/2011 3:20 p.m. | |
| By Whom? | Date and Hour – | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. RCVD AUG 10 '11 OIL CONS. DIV. | |
| If a Watercourse was Impacted, Describe Fully.* DIST. 3 | | |
| Describe Cause of Problem and Remedial Action Taken.* The gas was found to be leaking at the water dump valve. Upon discovery, the valve was fully opened and a small obstruction was removed from in between the seat and trim of the water dump valve. The leak stopped once the obstruction was removed. The loss of gas was calculated over a seven (7) day period. | | |
| Describe Area Affected and Cleanup Action Taken.* All natural gas was vented to the atmosphere. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature: <i>Kelsi Harrington</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Kelsi Harrington | Approved by District Supervisor: <i>Brandon Powell</i> | |
| Title: Field Environmental Specialist | Approval Date: <i>8/17/11</i> | Expiration Date: |
| E-mail Address: kelsi.g.harrington@conocophillips.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 8/8/2011 | Phone: 505-599-3403 | |

* Attach Additional Sheets If Necessary

NJK 1123155139